



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19012668/Esd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 15-10-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7072X	Veh. Inspected	FP 9353S
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19070170	Excess (\$)	0.00
Assign From	CARINE KEK	Assign Date	16/09/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA RXZ	c.c	133
Engine No.	HIDDEN	Year of Reg.	1998
Chassis No.	ZMC232893	Colour	RED
Odometer	98179	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	2.50-18	VIVA	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	2.50-18	VIVA	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/07/2019	Inspection Date	18/07/2019
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------