

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879      Email : automaxsurvey@gmail.com

Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the ALL portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair :    10    working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : FP9353S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Headlamp assy	missing	\$ 435.00	\$ 435.00
1 pc	Headlamp casing with signal assy	Destory	\$ 108.00	\$ 108.00
1 pc	Front mudguard	deformed	\$ 113.30	\$ 113.30
1 pc	Rim	bent/distorted	\$ 250.00	\$ 250.00
1 set	Front fork cover	grazed/deformed	\$ 94.00	\$ 94.00
2 pcs	Front fork tube	bent/distorted	\$ 280.00	\$ 280.00
2 pcs	Front fork oil seal	grazed/deformed	\$ 104.00	\$ 104.00
1 pc	Handle bar	bent/distorted	\$ 208.00	\$ 208.00
1 set	Handle bar grip	bent/distorted	\$ 88.00	\$ 88.00
2 pcs	Handle bar balance	grazed/deformed	\$ 88.00	\$ 88.00
1 pc	Main stand	bent/distorted	\$ 128.00	\$ 128.00
1 pc	Brake pedal	bent/distorted	\$ 95.00	\$ 95.00
1 pc	Front fork bracket	bent/distorted	\$ 115.00	\$ 115.00
1 pc	Steering cone	bent/distorted	\$ 145.90	\$ 145.90
1 pc	Front foot rest	grazed/deformed	\$ 85.00	\$ 85.00
1 pc	Kick starter	bent/distorted	\$ 186.00	\$ 186.00
1 pc	Body frame assy	bent - repair	\$ 1,880.00	\$ -
1 pc	Shift gear pedal	distorted	\$ 68.00	\$ 68.00
1 pc	Throttle handle	distorted	\$ 62.00	\$ 62.00
1 pc	Brake lever	distorted	\$ 65.00	\$ 65.00
1 pc	Clutch lever	distorted	\$ 65.00	\$ 65.00
1 pc	Meter assy	grazed/deformed	\$ 328.00	\$ 328.00
Parts Sub-Total			\$ 4,991.20	\$ 3,111.20
Discount 10.00%			\$ 499.12	\$ 311.12
			\$ 4,492.08	\$ 2,800.08

Vehicle Number : FP9353S

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Number plate	Necessary	\$ 88.00	\$ 88.00
2 blts	Fork oil	Necessary	\$ 60.00	\$ 60.00
2 blts	Brake oil	Necessary	\$ 60.00	\$ 60.00
1 pc	Meter cable	grazed/loose	\$ 65.00	\$ 65.00
1 pc	Throttle cable	grazed/loose	\$ 65.00	\$ 65.00
1 pc	Horn assy	open cicruit	\$ 65.00	\$ 65.00
1 pc	Tyre	deformed	\$ 200.00	\$ 200.00
1 pc	Brake pad	Necessary	\$ 25.00	\$ 25.00
1 pc	Brake disc	wrapped	\$ 183.00	\$ 183.00
1 pc	Front brake caliper	damaged	\$ 135.00	\$ 135.00
1 pc	ERP assy	Necessary	\$ 288.00	\$ 288.00
1 set	Sticker set	Necessary	\$ 65.00	\$ 65.00
Special Nett Sub-Total			\$ 1,299.00	\$ 1,299.00
Spare Parts Total			\$ 5,791.08	\$ 4,099.08

**LABOUR COST**

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
Spare PartsTotal c/f		\$ 5,791.08	\$ 4,099.08
1	Labour charges to repair and panel beat body frame structure cutting/welding and replacing the above mentioned parts.	\$ 1,600.00	\$ 1,400.00
2	Transport	\$ 100.00	\$ 100.00
3	To replace wiring harness system incl checking	\$ 180.00	\$ 180.00
Total		\$ 7,671.08	\$ 5,779.08

The repairer has agreed to undertake the repair under a Sum Basis. We have further adjusted the amount to Sum Repair of :

\$ 5,000.00

Fong Kok Heng  
Qualified Appraiser



# ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677978  
Tel: 6760 6271 Fax: 6764 6676

---

MUHAMMAD FAIROZ BIN HAFAZUL  
BLOCK 472 CHOA CHU KANG AVENUE 3  
#14-159  
SINGAPORE 680472

DATE: 08/09/20

DEAR SIRs

ACCIDENT DATE: 07/07/19  
FINAL REPAIR BILL TO FP 9535 S

**LUMP SUM REPAIRS RECOMMENDED**  
BY THE SURVEYOR-----\$ 5,000.00

DOLLARS: FIVE THOUSAND ONLY

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5107653499

Cover : Third Party

- |                                                  |                               |
|--------------------------------------------------|-------------------------------|
| 1. Index mark and Registration Number of Vehicle | : FP93535                     |
| Chassis Number                                   | : ZMC232893                   |
| 2. Name of Policyholder                          | : MUHAMMAD FAIROZ BIN HAFAZUL |
| 3. Effective Date of Insurance                   | : 19 Feb 2019                 |
| 4. Expiry Date of Insurance                      | : 18 Feb 2020                 |

5. Persons or Classes of Persons entitled to drive#

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: MUHAMMAD FAIROZ BIN HAFAZUL
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : CHUI WEI JEAT (00000602620)

Date of Issue : 19 Feb 2019 16:27 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive