

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

TO	: INDIA INTERNATIONAL	DATE	: 16/9/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT			
Xiao Tony			
VEHICLE DETAILS			
VEHICLE NO	: SFN99X		
VEHICLE MODEL	: BENTLEY FLYING SPURS		
CHASSIS NO	: SCBBE53W9DC082440		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XAVIER / 90079247	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>cracked</i>	2	\$ 104.00	\$ 208.00
2	REAR BUMPER <i>Distorted</i>	1	\$ 8,353.00	\$ 8,353.00
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 295.00	\$ 590.00
4	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 1,994.00	\$ 1,994.00
5	REAR BUMPER REINFORCEMENT BRACKET <i>Best</i>	2	\$ 347.00	\$ 694.00
6	REAR BUMPER CHROME MOULDING <i>new</i>	2	\$ 1,839.00	\$ 3,678.00
7	REAR BUMPER SPONGE <i>cracked</i>	1	\$ 715.00	\$ 715.00
8	REAR BUMPER EXHAUST TAIL PIPE <i>RH dented</i>	2	\$ 704.00	\$ 1,408.00
9	REAR BUMPER EXHAUST TAIL PIPE BRACKET <i>RH Best</i>	2	\$ 55.00	\$ 110.00
10	REAR BUMPER UNDERCOVER <i>Distorted</i>	1	\$ 772.00	\$ 772.00
11	REAR BUMPER LOWER GARNISH <i>Distorted</i>	1	\$ 1,965.00	\$ 1,965.00
12	REAR BUMPER REVERSE LAMP <i>RH cracked</i>	2	\$ 653.00	\$ 1,306.00
13	REAR BUMPER CAMERA <i>Damaged</i>	1	\$ 695.00	\$ 695.00
14	REAR BUMPER CENTRE BRACKET <i>cracked</i>	1	\$ 424.00	\$ 424.00
15	REAR BUMPER REVERSE SENSOR <i>Damaged</i>	2	\$ 886.00	\$ 1,772.00
16	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	2	\$ 68.00	\$ 136.00
17	REAR END PANEL <i>Dented</i>	1	\$ 1,473.00	\$ 1,473.00
18	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 458.00	\$ 458.00
19	TAILLAMP <i>RH cracked</i>	2	\$ 4,069.00	\$ 8,138.00
20	BOOTLID <i>Dented</i>	1	\$ 18,030.00	\$ 18,030.00
21	BOOTLID LOCK <i>Damaged</i>	1	\$ 895.00	\$ 895.00
22	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 675.00	\$ 675.00
23	BENTLEY LOGO <i>new</i>	1	\$ 581.00	\$ 581.00
24	SPARE TYRE PANEL TOP COVER <i>3 not</i>	1	\$ 938.00	\$ 938.00
25	TOOLS TRAY SPONGE <i>3 not</i>	1	\$ 785.00	\$ 785.00

26	REAR EXHAUST PIPE <i>Repair</i>	1	\$ 5,144.00	\$ 5,144.00	x
27	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 185.00	\$ 185.00	x

TOTAL PRICE: \$ 61,122.00
 LESS 10% \$ 6,112.20
 SUB TOTAL PRICE: \$ 55,009.80

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 100.00	\$ 100.00	✓
2	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 100.00	\$ 100.00	✓
3	REAR BUMPER UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 100.00	\$ 100.00	✓
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00	x
5	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 100.00	\$ 100.00	✓
TOTAL :				\$ 450.00	

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 2,000.00	1400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	1250	
3	WIRING CHECK	\$ 200.00	50	
4	TO APPLY TUFF COAT	\$ 200.00	100	
5	TO REMOVE REVERSE SENSOR	\$ 150.00	100	
	TO REMOVE REAR CAMERA	\$ 150.00	100	
6	TO REMOVE UPHOLSTERY	\$ 200.00	120	
7	TO TRANSFER BOOTLID FITTINGS	\$ 250.00	120	
8	TO REMOVE EXHAUST PIPE	\$ 250.00	150	
9	TO PERFORM DIAGNOSTIC TEST	\$ 300.00	150	

TOTAL: \$ 5,700.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 55,459.80

TOTAL LABOUR COST: \$ 5,700.00

TOTAL REPAIR COST: \$ 61,159.80

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify FAX:
the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed **and**
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1/5: 35.5K
 10 Days.

35.5K.
 10 Days.