

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869  
Tel : 6904 4596 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO: LKK - KENNETH  
Surveyor Name and Company

Date of Accident : 15-Sep-2020

BILL TO: MSIG  
TP Insurer

VEHICLE REG. NO.

**SJX7849C**

TYPE OF CLAIM: TP

Make / Model : TOYOTA COROLLA ALTIS 1.6 AUTO

COST OF REPAIR

Parts Cost / List : \$ 8,239.86

Supp. Parts : \$ 1,811.00

Special Nett : \$ 1,100.00

Total Parts : \$ 8,638.15

Total Labour : \$ 3,000.00

Total Parts Cost/List :	\$	10,050.86
Plus / Less : 25%	\$	2,512.72
<b>Total :</b>	\$	<b>7,538.15</b>

Lump Sum Discount : 20%	\$	2,327.63
Lump Sum Amount:	\$	9,310.52

TOTAL REPAIR COST : \$ 11,638.15 **33,294.79** Final Lump Sum Amount : \$ 9,300.00

Submitted by / Date : PAULO No. of Repair Days: 10

Confirmed by / Date : \_\_\_\_\_

**Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)**

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**  
 Vehicle Reg. Date: **12/7/2010**  
 Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUTO**  
 Engine No. : **3ZZ4998288**  
 Chassis No. : **MR053ZEE106175275**

PAGE 1

**Estimates on Parts**

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BONNET Repair		\$ 950.80		
2	1	BONNET HINGE RH Repair		\$ 65.20		
3	1	FRONT BUMPER mtg cracked		\$ 492.80		\$ 492.80
4	1set	FRONT BUMPER CLIPS NN		\$ 30.00		
5	1	FRONT BUMPER RETAINER RH Svc		\$ 51.70		
6	1	FRONT BUMPER SPONGE Svc		\$ 87.00		
7	1	WASHER TANK Svc		\$ 140.70		
8	1	FOG LAMP RH Svc		\$ 267.80		
9	1	FOG LAMP GARNISH RH Svc		\$ 130.90		
10	1	FRONT FENDER RH Bent		\$ 622.10		\$ 622.10
11	1	FRONT FENDER EMBLEM RH Nec		\$ 60.30		\$ 60.30
12	1	FRONT FENDER INNER SHIELD RH Distorted		\$ 171.20		\$ 171.20
13	1set	FRONT FENDER INNER SHIELD CLIPS Nec		\$ 20.00		\$ 20.00
14	1	FRONT FENDER APRON RH Repair		\$ 474.80		
15	1	FRONT FENDER GARNISH RH Svc		\$ 40.70		
16	1	FRONT RIM RH Dented			\$ 400.00	280
17	1	FRONT TYRE RH \$180 (70%) cut			\$ 300.00	126
18	1	FRONT SHOCK ABSORBER RH Bent		\$ 351.80		\$ 351.80
19	1	FRONT SHOCK ABSORBER MOUNTING RH Svc		\$ 150.60		\$ 150.60
20	1	FRONT STABILIZER LINK RH Svc		\$ 98.40		
21	1	FRONT LOWER ARM RH Distorted		\$ 270.85		\$ 270.85
22	1	FRONT LOWER ARM BALL JOINT RH Svc		\$ 124.30		
23	1	FRONT WHEEL HUB RH Bent		\$ 228.10		\$ 228.10
24	1	FRONT KNUCKLE ARM RH Bent		\$ 521.50		\$ 521.50
25	1	FRONT WHEEL BEARING RH Nec		\$ 130.90		\$ 130.90
26	1	ROCKER PANEL RH Repair		\$ 876.52		
27	1	FRONT WINDSCREEN PILLAR RH Repair		\$ 377.40		
28	1	FRONT DOOR RH Bent		\$ 785.60		\$ 785.60
29	1	FRONT DOOR OUTER GARNISH RH Svc		\$ 157.85		\$ 157.85
30	1	FRONT DOOR WEATHERSTRIP RH 50% cut		\$ 210.70		\$ 210.70
31	1	FRONT DOOR LOCK Repair		\$ 685.40		
32	1	FRONT DOOR TOP HINGE RH Distorted		\$ 86.90		\$ 86.90
33	1	FRONT DOOR LOWER HINGE RH Bent		\$ 86.90		\$ 86.90
34	1	FRONT DOOR CHECKER RH Distorted		\$ 127.62		\$ 127.62
35	1	FRONT DOOR STRIKER RH Repair		\$ 65.80		
36	1	FRONT DOOR POWER WINDOW MOTOR RH	Jammed	\$ 687.95		\$ 687.95
37	1	FRONT DOOR OUTER HANDLE RH Distorted		\$ 98.70		\$ 98.70
38	1	FRONT DOOR INNER HANDLE RH Svc		\$ 218.16		
39	1	FRONT DOOR INNER TRIMBOARD RH Svc		\$ 876.59		\$ 876.59
40	1	FRONT DOOR OUTER MOULDING RH dented		\$ 95.84		\$ 95.84
				10,920.38	\$ 700.00	\$ 6,234.80

585.10

X

X

105.35 (SN)

X

**Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)**  
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869  
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**  
Vehicle Reg. Date: **12/7/2010**  
Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUTO**  
Engine No. : **3ZZ4998288**  
Chassis No. : **MR053ZEE106175275**

PAGE 2

**Estimates on Parts**

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	FRONT DOOR UPPER MOULDING RH Svc		\$ 157.00		
42	1	FRONT DOOR GLASS RH Svc		\$ 570.86		
43	1	SIDE MIRROR ASSY RH cracked		\$ 698.90		\$ 698.90
44	1	CENTER PILLAR RH Repair		\$ 852.90		
45	1	REAR DOOR RH Bent		\$ 987.76		\$ 987.76
46	1	REAR DOOR OUTER GARNISH RH Svc		\$ 157.85		
47	1	REAR DOOR WEATHERSTRIP RH Svc		\$ 210.70		\$ 210.70
48	1	REAR DOOR LOCK Repair		\$ 685.40		
49	1	REAR DOOR TOP HINGE RH Repair		\$ 86.90		
50	1	REAR DOOR LOWER HINGE RH Repair		\$ 86.90		
51	1	REAR DOOR CHECKER RH Svc		\$ 127.62		
52	1	REAR DOOR STRIKER RH Repair		\$ 65.80		
53	1	REAR DOOR POWER WINDOW MOTOR RH Svc		\$ 687.95		
54	1	REAR DOOR OUTER HANDLE RH Svc		\$ 95.20		
55	1	REAR DOOR INNERHANDLE RH Svc		\$ 200.15		
56	1	REAR DOOR INNER TRIMBOARD RH Svc		\$ 890.95		
57	1	REAR DOOR OUTER MOULDING RH nec		\$ 107.70		\$ 107.70
58	1	REAR DOOR UPPER MOULDING RH Svc		\$ 157.00		
59	1	REAR DOOR GLASS RH Svc		\$ 389.60		
60	1	REAR FENDER RH Repair		\$ 560.70		
61	1	REAR FENDER INNER SHIELD RH Svc		\$ 60.70		
62	1set	REAR FENDER INNER SHIELD CLIPS NN		\$ 20.00		
63	1	REAR RIM RH dented			\$ 400.00	280
64	1	REAR TYRE RH Svc				
65	1	REAR SHOCK ABSORBER RH Svc		\$ 189.90		
66	1	REAR WHEEL HUB ASSY RH Svc		\$ 587.95		
67	1	REAR BEAM ASSY Svc		\$ 1,950.85		
68	1	REAR BUMPER svc		\$ 594.70		
69	1set	REAR BUMPER CLIPS NN		\$ 30.00		
70	1	REAR BUMPER RETAINER svc		\$ 80.92		
71	1	DASH BOARD COVER Svc		\$ 870.55		
72	1	ROCKER PANEL SEALANT NN				
73	1	REAR FENDER SEALANT NN				
74	1	SUNDRIES NN				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

12,163.41 \$ 400.00 \$ 2,005.06



**Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)**

44 Benoi Road, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**  
Vehicle Reg. Date: **12/7/2010**  
Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUT**  
Engine No. : **3ZZ4998288**  
Chassis No. : **MR053ZEE106175275**

ATTN:  
PLEASE QUOTE LIST PRICE  
FAX:

PAGE 1

**Supplementary Estimates on Parts**

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	HEAD LAMP RH <i>mtg cracked</i>		\$ 608.70		\$ 608.70
2	1	ROCKER PANEL GARNISH RH <i>Distored</i>		\$ 734.50		\$ 734.50
3	1	FRONT FENDER SEAL RH <i>cracked</i>		\$ 86.70		\$ 86.70
4	1	FRONT A PILLAR RH <i>Bent</i>		\$ 381.10		\$ 381.10
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

1811.00

\$ 1,811.00

**Tel : 6904 4596 | Fax No : 6694 4929**

[illegible]

Menorah (Utk) Not Authorised  
 6/1/2010  
 Murray After Paint  
 Today

Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)  
 60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869  
 Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**  
 Vehicle Reg. Date: **12/7/2010**  
 Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUTO**  
 Engine No. : **3ZZ4998288**  
 Chassis No. : **MR053ZEE106175275**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BONNET	R X			
2	1	BONNET HINGE RH	R X			
3	1	FRONT BUMPER	Sn X			
4	1set	FRONT BUMPER CLIPS	Sn X			
5	1	FRONT BUMPER RETAINER RH	Sn X			
6	1	FRONT BUMPER SPONGE	Sn X			
7	1	WASHER TANK	Sn X			
8	1	FOG LAMP RH	Sn X			
9	1	FOG LAMP GARNISH RH	Sn X			
10	1	FRONT FENDER RH	R X			
11	1	FRONT FENDER EMBLEM RH	Sn			
12	1	FRONT FENDER INNER SHIELD RH	D/I			
13	1set	FRONT FENDER INNER SHIELD CLIPS	Sn			
14	1	FRONT FENDER APRON RH	R X			
15	1	FRONT FENDER GARNISH RH	Sn X			
16	1	FRONT RIM RH	R		\$ 400.00	
17	1	FRONT TYRE RH			\$ 300.00	
18	1	FRONT SHOCK ABSORBER RH	X			
19	1	FRONT SHOCK ABSORBER MOUNTING RH	X			
20	1	FRONT STABILIZER LINK RH	Sn			
21	1	FRONT LOWER ARM RH	X			
22	1	FRONT LOWER ARM BALL JOINT RH	Sn			
23	1	FRONT WHEEL HUB RH	X			
24	1	FRONT KNUCKLE ARM RH	X			
25	1	FRONT WHEEL BEARING RH	X			
26	1	ROCKER PANEL RH	R			
27	1	FRONT WINDSCREEN PILLAR RH	R			
28	1	FRONT DOOR RH	B			
29	1	FRONT DOOR OUTER GARNISH RH	Sn			
30	1	FRONT DOOR WEATHERSTRIP RH				
31	1	FRONT DOOR LOCK	R			
32	1	FRONT DOOR TOP HINGE RH	D/I			
33	1	FRONT DOOR LOWER HINGE RH	R			
34	1	FRONT DOOR CHECKER RH	Sn			
35	1	FRONT DOOR STRIKER RH	R			
36	1	FRONT DOOR POWER WINDOW MOTOR RH	X			
37	1	FRONT DOOR OUTER HANDLE RH	D/I			
38	1	FRONT DOOR INNERHANDLE RH	Sn			
39	1	FRONT DOOR INNER TRIMBOARD RH	Sn			
40	1	FRONT DOOR OUTER MOULDING RH	Sn			

HEAD LAMP RH

ROCKER PANEL GARNISH RH D/I

?



**Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)**  
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869  
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**  
Vehicle Reg. Date: **12/7/2010**  
Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUTO**  
Engine No. : **3ZZ4998288**  
Chassis No. : **MRO53ZEE106175275**

PAGE 2

**Estimates on Parts**

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	FRONT DOOR UPPER MOULDING RH <i>Sm</i>				X
42	1	FRONT DOOR GLASS RH <i>Sm</i>				X
43	1	SIDE MIRROR ASSY RH <i>CM 52</i>				X
44	1	CENTER PILLAR RH <i>R</i>				X
45	1	REAR DOOR RH <i>B</i>				X
46	1	REAR DOOR OUTER GARNISH RH <i>Sm</i>				X
47	1	REAR DOOR WEATHERSTRIP RH <i>Sm</i>	<i>* ✓</i>			X
48	1	REAR DOOR LOCK <i>R</i>				X
49	1	REAR DOOR TOP HINGE RH <i>R</i>				X
50	1	REAR DOOR LOWER HINGE RH <i>R</i>				X
51	1	REAR DOOR CHECKER RH <i>Sm</i>				X
52	1	REAR DOOR STRIKER RH <i>R</i>				X
53	1	REAR DOOR POWER WINDOW MOTOR RH <i>Sm</i>				X
54	1	REAR DOOR OUTER HANDLE RH <i>Sm</i>				X
55	1	REAR DOOR INNERHANDLE RH <i>Sm</i>				X
56	1	REAR DOOR INNER TRIMBOARD RH <i>Sm</i>				X
57	1	REAR DOOR OUTER MOULDING RH <i>Sm</i>				X
58	1	REAR DOOR UPPER MOULDING RH <i>Sm</i>				X
59	1	REAR DOOR GLASS RH <i>Sm</i>				X
60	1	REAR FENDER RH <i>R</i>				X
61	1	REAR FENDER INNER SHIELD RH <i>Sm</i>				X
62	1set	REAR FENDER INNER SHIELD CLIPS <i>Nu</i>				X
63	1	REAR RIM RH <i>Ad Box</i>			\$ 400.00	X
64	1	REAR TYRE RH <i>Sm</i>			\$ 300.00	X
65	1	REAR SHOCK ABSORBER RH <i>Sm</i>				X
66	1	REAR WHEEL HUB ASSY RH <i>SLC</i>				X
67	1	REAR BEAM ASSY <i>R</i>				X
68	1	REAR BUMPER <i>Sm</i>				X
69	1set	REAR BUMPER CLIPS <i>Nu</i>				X
70	1	REAR BUMPER RETAINER <i>Sm</i>				X
71	1	DASH BOARD COVER <i>Sm</i>	<i>Not Condition</i>			X
72	1	ROCKER PANEL SEALANT <i>Nu</i>			\$ 100.00	X
73	1	REAR FENDER SEALANT <i>Nu</i>			\$ 100.00	X
74	1	SUNDRIES			\$ 60.00	7
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

**Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)**

44 Benoi Road, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**  
Vehicle Reg. Date: **12/7/2010**  
Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUT**  
Engine No. : **3ZZ4998288**  
Chassis No. : **MR053ZEE106175275**

PAGE 1

**Supplementary Estimates on Parts**

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	HEAD LAMP RH *	✓			
2	1	ROCKER PANEL GARNISH RH *	✓			
3	1	FRONT FENDER SEAL RH *	✓			
4	1	FRONT A PILLAR RH *	✓			
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						



**Tel : 6904 4596 | Fax No : 6694 4929**

PAGE 1

[illegible]

Customer:		Date:	17-Sep-20 4:43 PM
Company:		VIN	
License No:	SJX7849C	Technician:	IVAN
Odometer:		Order No.:	

## VEHICLE ALIGNMENT REPORT

TOYOTA (MY), ALTIS, 2008-2008, ZZE 14

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2.1°	3.6°	----
		Right	----	2.1°	3.6°	----
	Camber	Left	-0.5°	-1.3°	0.2°	-1.6°
		Right	-0.8°	-1.3°	0.2°	-2.2°
	Toe	Left	-0.10°	-0.10°	0.10°	0.00°
		Right	0.00°	-0.10°	0.10°	-3.55°
Total		-0.10°	-0.20°	0.20°	-3.55°	
Rear	Camber	Left	-1.8°	----	----	-1.9°
		Right	-1.5°	----	----	-3.7°
	Toe	Left	0.20°	----	----	0.35°
		Right	-0.15°	----	----	2.70°
		Total	0.05°	----	----	3.05°
Thrust Angle		-0.2°	----	----	1.2°	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	----	11.8°	13.3°	----	
	Right	----	11.8°	13.3°	----	
Included Angle	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Out On Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Maximum Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	0mm	----	----	9mm	
	Rear	0mm	----	----	-1mm	
Track Width Diff.		-2mm			-2mm	
Wheel Base Diff.		0mm			10mm	
Front Ride Height	Left	----	----	----	x ----	
	Right	----	----	----	----	
Rear Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Frame Angle					----	

Customer:		Date:	25-Sep-20 12:02 PM
Company:	VERMOGEN ACE	VIN	
License No:	SJX7849C	Technician:	BIN
Odometer:		Order No.:	

## VEHICLE ALIGNMENT REPORT

TOYOTA (MY), ALTIS, 2008-2008, ZZE 14

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2.1°	3.6°	----
		Right	----	2.1°	3.6°	----
	Camber	Left	-0.7°	-1.3°	0.2°	-0.7°
		Right	-0.3°	-1.3°	0.2°	-0.3°
	Toe	Left	0.15°	-0.10°	0.10°	0.10°
		Right	-0.20°	-0.10°	0.10°	0.10°
Total		-0.05°	-0.20°	0.20°	0.20°	
Rear	Camber	Left	----	----	----	----
		Right	----	----	----	----
	Toe	Left	----	----	----	----
		Right	----	----	----	----
		Total	----	----	----	----
Thrust Angle		----	----	----	----	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	11.8°	13.3°	----
	Right		----	11.8°	13.3°	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		0mm	----	----	-6mm
	Rear		----	----	----	----
Track Width Diff.			0mm			0mm
Wheel Base Diff.			----			----
Front Ride Height	Left		----	----	----	X
	Right		----	----	----	
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----