

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 120/IC/TCAC/SAY/2020
DATE : 15-SEP-2020

FIRST CAPITAL INSURANCE LTD REFER MS FIRST
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848 / 68543466
FAX : 65073849
ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : MISS MEREDITH YEUNG TSZ LING (YANG ZILING)
ADDRESS : 86 CORPORATION ROAD
#07-11 CONDO
S(649822)
TELEPHONE NO : 83225296

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100416126-05
VEHICLE NO : SGD905K
MODEL CODE : JDRNRRZT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20723761B
CHASSIS NO : JN1JANT32Z0000530
MILEAGE : 99200 KM
DATE IN : 15/09/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 14/09/2020

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGD905K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	.00 X
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00 X
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00 ✓
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00 X
5	ZZ/001	CONDUCT TP CLAIM MS FIRST CAP DATE:14/09/2020 TIME:1750HRS LOCATION:AYE TOWARDS TUA NUH FLYOVER		
6	ZZ/002	REPAIR/REPLACE REAR BUMPER,RR ENDPANEL , LH FENDER,RH FENDER & TAILGATE	1950.00	780.00 ✓
7	ZZ/003	RESPRAY REAR BUMPER,ENDPANEL,LH RR FENDER, RG RR FENDER & TAILGATE	1250.00	800.00 ✓
8	ZZ/004	REMOVE& REFIX REAR WINDSCREEN	240.00	.00 X
9	ZZ/005	SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	144.00	.00 X
TOTAL LABOUR CHARGES			3919.00	1635.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGD905K

				DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION		PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	PROTECTOR ASSY (SUPP)	✓ DD	64798-4CLMH	162.50			OK
2	GLASS-TAIL GATE	✗ NN	90300-4CCOA	1386.00			X
3	PROTECTOR-REAR FENDER LINER LH	✗ NN	76749-4CCOB	88.40			X
4	PROTECTOR-REAR RH FENDER LINER	✗ NN	76748-4CCOB	88.40			X
5	EMBLEM LOGO	✓ NEC	84895-4CLOA	110.00			OK
6	EMBLEM LETTERING	✓ NEC	84890-4CLOA	64.90			OK
7	SENSOR-REVERSE 4 EYES	✓ BR	SENSOR			360.00	OK
8	REAR W/SCREEN SEALANT	✗ NN	SEALANT - 4			80.00	X
9	DOOR BACK TAILGATE	✗ Repair	9001A-4CC5C	4380.00			X
10	FACE-RR BUMPER	✓ DD	85022-4CE0H	693.10			OK
11	BRACKET-BUMPER RH	✗ NN	85220-4CE0A	38.90			X
12	BRACKET-BUMPER LH (SUPP)	✓ BR	85221-4CE0A	38.80			OK
13	REINF-BUMPER RR REINFORCEMENT	✗ NN	85032-4CCOA	596.20			X
14	PANEL-REAR UPPER	✗ NN	79110-4CCOA	447.50			X
SUB TOTAL				1069.30	0.00	360.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)				213.86	0.00	0.00	
GRAND TOTAL				855.44	0.00	360.00	
OVERALL TOTAL				1215.44			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGD905K

NETT ITEM	1069.30
LESS 20.00%)	-213.86
NETT AMOUNT	855.44

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	360.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	360.00

TOTAL LABOUR CHARGES	1635.00
TOTAL SPARE PARTS CHARGES	1215.44

TOTAL CHARGES	2850.44
ADD 7 % GST	199.53

GRAND TOTAL	3049.97
-------------	---------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: