

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 120/IC/TCAC/SAY/2020
DATE : 15-SEP-2020

FIRST CAPITAL INSURANCE LTD REFER MS FIRST
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848 / 68543466
FAX : 65073849
ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : MISS MEREDITH YEUNG TSZ LING (YANG ZILING)
ADDRESS : 86 CORPORATION ROAD
#07-11 CONDO
S(649822)
TELEPHONE NO : 83225296

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100416126-05
VEHICLE NO : SG0905K
MODEL CODE : JDRNRRZT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20723761B
CHASSIS NO : JN1JANT32Z0000530
MILEAGE : 99200 KM
DATE IN : 15/09/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 14/09/2020

AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGD905K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	X
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	?
3 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	?
5 ZZ/001	CONDUCT TP CLAIM MS FIRST CAP DATE:14/09/2020 TIME:1750HRS LOCATION:AYE TOWARDS TUA NUH FLYOVER		
6 ZZ/002	REPAIR/REPLACE REAR BUMPER,RR ENDPANEL , LH FENDER,RH FENDER & TAILGATE ¹ 390	1950.00	780
7 ZZ/003	RESPRAY REAR BUMPER,ENDPANEL,LH RR FENDER, RG RR FENDER & TAILGATE ¹ 250	1250.00	800
8 ZZ/004	REMOVE & REFIX REAR WINDSCREEN	240.00	?
9 ZZ/005	SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	144.00	?
TOTAL LABOUR CHARGES		3919.00	

5 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGD905K

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SENSOR-REVERSE 4 EYES	SENSOR		360.00 ✓
2	REAR W/SCREEN SEALANT ?	SEALANT - 4		80.00
3	DOOR BACK TAILGATE X R	9001A-4CC5C	4380.00	
4	GLASS-TAIL GATE X	90300-4CC0A	1386.00	
5	PROTECTOR-REAR FENDER LINER LH X	76749-4CC0B	88.40	
6	PROTECTOR-REAR RH FENDER LINER X	76748-4CC0B	88.40	
7	EMBLEM LOGO ✓ ne	84895-4CLOA	110.00	
8	EMBLEM LETTERING ✓ ne	84890-4CLOA	64.90	
9	FACE-RR BUMPER ✓ 00	85022-4CE0H	693.10	
10	BRACKET-BUMPER RH ?	85220-4CE0A	38.90	
11	BRACKET-BUMPER LH ? ✓ BR	85221-4CE0A	38.80	
12	REINF-BUMPER RR REINFORCEMENT ?	85032-4CC0A	596.20	
13	PANEL-REAR UPPER ? X	79110-4CC0A	447.50	
SUB TOTAL			7932.20	0.00 440.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1586.44	0.00 0.00
GRAND TOTAL			6345.76	0.00 440.00
OVERALL TOTAL			6785.76	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGD905K

TOTAL LABOUR CHARGES	3919.00
TOTAL SPARE PARTS CHARGES	6785.76
GRAND TOTAL	10704.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

83228813

Steve (LKK)

21/9/20, 10.00am

5 days

P/P

Ry Bel H

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: