

REPAIR ESTIMATE*

DATE 17/09/20

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER			\$1,052.20
1	FRONT BUMPER BRACKET RH			\$24.60
1	FRONT RH WING MIRROR			\$670.00
1	FRT DOOR OUTER MOULDING			\$53.10
1	HEADLAMP RH			\$1,388.00
1	HEAD LAMP SUPPORT PANEL			\$907.40
1	FRONT FENDER SHIELD RH			\$174.90
1	FRONT FENDER RH			\$663.00
1	FRONT S/ ABSORBER RH			\$342.00
1	FRONT S/ABSOBER MTG			\$217.60
1	FRONT SUSPENSION LOWER ARM RH			\$595.90
1	FRT RH KNUCKLE ARM			\$1,104.00
1	FRT RH STRG TIE ROD			\$135.00
1	FRT RH STRG TIE BALL JOINT			\$73.10
1	FRT RH STABILIZER LINK			\$68.10
1	FRONT WHHEL RIM RH			\$650.60
1	FRONT WHEEL COVER RH			\$107.10
	SUB TOTAL			\$8,226.60
	20.00%			\$1,645.32
	DISCOUNTED TOTAL			\$6,581.28
1	FRONT DOOR COMFORT LOGO STICKER			\$75.00
1	FRT RH TYRE HANKOOK			\$216.00
				\$291.00
	Labour Charge			
	Panel Beating			\$720.00
	Spray Painting Charge			\$640.00
	Remove/replace frt under suspension			\$120.00
	Remove/refix radiator			\$90.00
	Reset front wheel alignment			\$90.00
	Towing fees			\$60.00
	Tuff Kote			\$90.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,870.00
	ESTIMATE TOTAL			\$8,742.28
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

200, Bras Basah Road, Singapore 179571
 Mobile: +65 6 833 8200 Fax: +65 6 833 9255

Workshops

1001, Joo Yang Estate, Singapore 130009
 1003, Tanjong Pagar, Singapore 100417
 15, Tanjong Pagar, Singapore 100406

24, Selegie Road, Singapore 118246
 7, Selegie Road, Singapore 118231
 201, Selegie Road, Singapore 118218

A member of COMFORTDELGRO

Date/Time: 17.09.2020 08:29

Page: 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305423028

STOMER

/MS COMFORT TRANSPORTATION PTE LTD
 STOMER NO 7010045
 DRESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 (R) 65508755 (O)

REGN NO: SHA5318B

MAKE: HYUNDAI

MODEL I-40

YR OF MANU 25.01.2017

CHASSIS CODE KMHLB41UMHU098297

MILEAGE

FUEL

E 1/2 F

DATE/TIME IN 16.09.2020 13:05

TARGET DATE

COMPLETION DATE/TIME

ACCOUNT CARD NO.

JOB DESCRIPTION


Accident Date: 16.09.2020

NATURE: 3P 16.09.20020

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHA5318B

CHIANG

Vehicle No.:

SHA5318B

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard