

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009959/UBA3Q2
Date: 03/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070087671	
Claimant Vehicle No :	YP3691E	Insured Vehicle No :	YP6623H	
Date of Loss:	15/09/2020	Nature of Claim:	TP	Claim No: 4764614675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP3691E		
Make & Model:	MITSUBISHI FEB21CR4SDEB, 3.0 D (M)	Engine No:	4P10C19708
Reg. Date:	29/07/2016 (Man. Year: 2016)	Chassis No:	FEB21CA20045
Colour:	White	Odometer:	281967 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,876.10	3,314.33	2,561.77	43.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	1,070.00	310.00	22.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,256.10	4,384.33	2,871.77	39.58
Approved Total (Overridden) (S\$)		3,500.00		

Nett Amount (S\$)	7,256.10	3,500.00	3,756.10	51.76
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
Nett Liability (S\$)		3,900.00		
Global Sum Settlement (S\$)		3,800.00		

INSPECTION

Date of Assignment: 17/09/2020

Date Inspected: 17/09/2020 Inspected At: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)
 Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Badly Dented	2,001.50 F	*2,001.50 FL
2	2		*FRONT RH DOOR HINGES	Not Necessary	218.20 F	*- FL
3	1		*FRONT RH DOOR VIEW MIRROR	Broken	112.50 F	*112.50 FL
4	1		*FRONT RH CORNER PANEL	Deformed / Cracked	474.60 F	*474.60 FL
5	1		*FRONT RH SIGNAL LAMP	Broken	324.30 F	*324.30 FL
6	1		*SET FRONT RH SIGNAL LAMP CLIPS	Not Necessary	20.00 FS	*- FS
7	1		*FRONT RH SIDE LAMP	Broken	235.20 F	*235.20 FL
8	1		*FRONT RH HEAD LAMP	Cracked	856.40 F	*856.40 FL
9	1		*SET FRONT RH HEAD LAMP CLIPS	Not Necessary	30.00 FS	*- FS
10	1		*FRONT RH BUMPER	Repair	1,133.40 F	*- FL
11	1		*SET FRONT RH BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
12	1		*FRONT RH BUMPER SIDE	Scratched	375.00 F	*354.61 FL
13	1		*SET FRONT RH BUMPER SIDE CLIPS	Necessary	45.00 FS	*45.00 FS
					Sub Total (\$)	5,876.10
					- List Item Discount on L Items 0.00/25.00% (\$)	0.00
					Total Parts (\$)	3,314.33

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	40.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	520.00	400.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	680.00	550.00
4	TO REMOVE ,REPLACE AND TRANSFER DOOR PANEL ,FITTING AND MECHANISMS	New	80.00	60.00
5	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	40.00
Gross Labour Cost (S\$)			1,380.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >