

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

16 Sep 2020

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Not Authorized
17/9/20
2 hrs.

THIRD PARTY CLAIM

OWNER NAME : ONG WOO THIAM
VEHICLE REG NO : SJT1259R
DATE OF ACCIDENT : 15 SEP 2020
PLACE OF ACCIDENT : BLK 219 PASIR RIS ST 21
INVOLVING VEH NO : SLE5137M

We append herewith our estimate for the repair of Vehicle No SJT1259R as follows:

Materials Required

1 pc Rear Bumper	22	S\$1,815.80	✓
1 pc pc Rear Bumper Moulding	11	S\$ 486.20	✓
1 pc Rear Bumper Retainer RH	11	S\$ 65.80	✓
1 pc Rear Bumper Bracket RH	11	S\$ 45.60	✓
1 pc Rear Bumper Towing Cover	11	S\$ 75.20	✓
10 pcs Rear Bumper Clips	11	S\$ 75.00	✓
1 pc Taillamp RH	11	S\$ 690.40	✓
1 pc Reverse Sensor	11	S\$ 319.00	✓
		S\$3,573.00	

Labour Charges

To dismantle & replace damaged parts, panelbeat where necessary	S\$ 400.00	200
To putty, apply primer & spraypaint affected portion	S\$ 450.00	200
To apply rustproofing on repaired, replaced panel	11 S\$ 100.00	✓
To check electrical wiring functions	S\$ 80.00	50
	S\$4,603.00	

SUPER-ZEE MOTOR SERVICE

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Business Registration No. 47959700J