

# SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565  
EMAIL: superzeemotor@gmail.com

16 Sep 2020

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

Not Authorised  
11/9/20  
c/s #1800  
2 lgs.

## THIRD PARTY CLAIM

OWNER NAME : ONG WOO THIAM  
VEHICLE REG NO : SJT1259R  
DATE OF ACCIDENT : 15 SEP 2020  
PLACE OF ACCIDENT : BLK 219 PASIR RIS ST 21  
INVOLVING VEH NO : SLE5137M

We append herewith our estimate for the repair of Vehicle No SJT1259R as follows:

### Materials Required

1 pc	Rear Bumper	1635.22	122	S\$1,815.80	✓
1 pc	Rear Bumper Moulding	3 pcs 422	121	S\$ 486.20	✓
1 pc	Rear Bumper Retainer RH		11	S\$ 65.80	X
1 pc	Rear Bumper Bracket RH		11	S\$ 45.60	X
1 pc	Rear Bumper Towing Cover		11	S\$ 75.20	X
10 pcs	Rear Bumper Clips	60.00	121	S\$ 75.00	✓
1 pc	Taillamp RH		11	S\$ 690.40	X
1 pc	Reverse Sensor		11	S\$ 319.00	X
				S\$3,573.00	

### Labour Charges

To dismantle & replace damaged parts, panelbeat where necessary	S\$ 400.00	200
To putty, apply primer & spraypaint affected portion	S\$ 450.00	200
To apply rustproofing on repaired, replaced panel	S\$ 100.00	X
To check electrical wiring functions	S\$ 80.00	50
		S\$4,603.00

SUPER-ZEE MOTOR SERVICE

*[Handwritten signature]*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Business Registration No. 47959700J

2,217.22  
c/s 1800