

祥輝汽車修理
 SIANG HUI MOTOR WORKS
 Blk 3006, Ubi Road 1 #01-338, Singapore 408700.
 Tel: 67444805 Fax: 67441728
 REG. No. 32226/00M
 Not Authorised
 21/09/20
 21/09/20
 Vehicle No: SGA 6643 S
 Date: 21/09/20

12	1 set 10 sets	Bumper clip @ \$15.00 ^{new} \$	50.00 S/Nett ✓
13	1 set	Reverse Sensor should \$	200.00 S/Nett ✓

the Repair of the following:

- To return before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be returned and is subject to final approval from Insurance Company

Acknowledged by Repairer