

Certification for Bus Repairs

SBS Transit

CBR REF NO. : HG20203873

Depot : HG

Report No.: W35082020

BUS VEHICLE NO. : SG1773J

Driver's Co no. & Name : 17047 Krishnamoorthy A/L Doraisamy

Accident Date : 04/09/2020

Date in : 05/09/2020

Date Out : 24/09/2020

Yr Of Reg	Make / Model	Chassis No.
2018	MAN A22 EU6, SD, AC, 2 Axle	WMAA22ZZ8JF006951

Stock Code	Description	Quantity	Total Material cost (S\$)
		0	\$0.00
30730009	BOSTICK SEALANT 7008 ✓ NEC	2	\$31.00
30122030	FLAP DOOR FL~GL+FR~GR;0.25X0.3M ✓ CUT	1	\$79.00
30400320	SIDE PANEL R8.E6 ✓ CUT	1	\$229.00
TOTAL FOR PARTS			S\$ 339.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	192.00
2	Contractor's repair charges	S\$	1200.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 1392.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 1731.00

2 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: