

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
1/1 Day &
Return After Paint
18 days

REPAIR ESTIMATE FOR SLT7464B

No.	Qty	List Items			
1	1	Front bumper	Avulom	\$ 614.60	✓
2	1	Front bumper lower chrome moulding	\$ Di	153.10	✓
3	2	Front bumper fog lamp cover	Nism	\$ 161.80	✓
4	2	Front bumper side retainer	\$ Di	47.80	✓
5	1 set	Front bumper clips	\$ N	30.00	✓
6	1	Front bumper inner reinforcement	\$ B	453.10	✓
7	2	Front bumper inner foam	\$ CM	291.60	✓
8	1	Front grille assy	\$ CM	390.30	✓
9	1	Front grille centre "NISSAN" logo	\$ CM	59.70	✓
10	2	Headlamp	CM	\$ 4,704.00	✓
11	1	Front bonnet	\$ Bu	991.90	✓
12	1	Front bonnet insulator	\$ CM	154.70	✓
13	1 set	Front bonnet insulator clips	\$ N	60.00	✓
14	1	Front bonnet lock	\$ B	93.20	✓
15	2	Front bonnet hinge	\$ Di	112.20	✓
16	1	Front support panel top	\$ B	263.30	✓
17	1	Front support panel lower	\$	353.30	✓
18	1	Front brace panel	\$ B	97.30	✓
19	2	Front fender	\$ Bu	1,166.80	✓
20	1	Air cleaner box	\$	586.40	✓
21	1	Inlet manifold	\$	864.70	✓
22	1	Front windscreen glass	\$ CM	1,281.00	✓
23	1 set	Front windscreen moulding	\$ N	143.60	✓
24	2	Front wiper side 1/4 garnish	\$	78.00	✓
25	1	Steering air bag	Avulom	\$ 2,126.80	✓
26	1	Steering wheel Airbag Spiral module	\$ N	216.00	✓
27	1	Passanger air bag	Avulom	\$ 2,390.20	✓
28	1	Air bag ECU	\$ N	1,445.00	✓
29	2	Front seat belt	\$ Tm	1,459.60	✓
30	1	Dashboard assy	\$ T1	1,665.80	✓
31	1	Rear bumper	\$ Bu	632.80	✓
32	2	Rear bumper reflector	Nism	\$ 127.00	✓
33	1 set	Rear bumper clips	\$ N	30.00	✓
34	2	Rear bumper side retainer	\$ Di	133.20	✓
35	2	Rear bumper inner reinforcement	\$ B	533.80	✓
36	1	Rear tailgate	\$ CM	4,200.00	✓
37	1	Rear tailgate centre "NISSAN" logo	\$ N	59.70	✓
38	1	Rear tailgate LH "C-TRAIL" emblem	\$ N	101.30	✓
39	1	Rear tailgate windscreen moulding	\$ N	76.50	✓
40	1	Rear tailgate inner trim board	\$ CM	452.60	✓
41	1 set	Rear tailgate inner trim board clips	\$ N	60.00	✓
42	1	Rear tailgate top lock	\$ N	557.90	✓
43	1	Rear tailgate lower lock catch	\$ R	42.20	X
44	1	Rear tailgate weatherstrip	\$ N	133.80	X
45	1	Rear end panel	\$	447.50	✓

46	1	Rear end panel top garnish			
47	1	Rear floor panel top cover	\$	73.20	?
48	1	Rear floor panel top board	\$	164.00	?
49	2	Rear fender wheel arch garnish	\$	915.80	?
50	1	Lower exhaust silencer/pipe assy	\$	372.00	?
51	1	Lower centre exhaust silencer/pipe assy mounting	\$	1,282.00	?
52	2	Rear lower exhaust silencer mounting	\$	28.50	?
53	1	Rear lower exhaust silencer top heat shield	\$	57.00	?
			\$	126.80	?
			\$	33,063.40	
		Less 10%	\$	3,306.34	
		Total :	\$	29,757.06	

Special Nett Items

54	1	Front number plate	\$	45.00	✓
55	2	Front bumper fog lamp	\$	643.20	X
56	1	Air cleaner box air duct	\$	367.20	✓
57	1	Air con condenser	\$	743.20	✓
58	1	Air con condenser pipe	\$	196.20	?
59	1	Radiator	\$	687.40	?
60	1	Radiator fan cowl/motor assy	\$	1,008.60	?
61	1	Radiator top hose	\$	47.30	?
62	1	Radiator lower hose	\$	53.10	?
63	1	Horn	\$	95.50	?
64	1 set	Front windscreen sealant	\$	50.00	401sn
65	1	IU bracket	\$	28.00	✓
66	1 set	Rear windscreen sealant	\$	50.00	401sn
67	1	Rear number plate	\$	45.00	✓
68	1 set	Rear end panel/floor panel sealant	\$	50.00	?
69	1 set	Reverse sensors (4 pcs)	\$	500.00	320sn
		Total :	\$	4,609.70	

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	2,200.00	140d
2	To putty and spray Spray Paintings charges.	\$	2,000.00	160d
3	To remove, refit air con condenser, radiator & refill gas.	\$	150.00	100d
4	To check wirings and lightings for front & rear portion.	\$	60.00	40d
5	To remove, refit front windscreen glass.	\$	140.00	120d
6	To remove, refit dashboard assy	\$	250.00	✓
7	To remove, refit both front seat belts, ECU, steering wheel spiral module, including reset air bag systems.	\$	200.00	180d
8	To remove, refit tailgate fittings.	\$	80.00	60d
9	To remove, refit rear windscreen glass.	\$	140.00	120d
10	To remove, refit reverse sensors.	\$	80.00	60d
11	To remove, refit rear upholstery and attachments.	\$	120.00	✓
12	To remove, refit lower exhaust silencer/pipe & rear lower exhaust silencer.	\$	100.00	60d

13 To mount vehicle on chassis bench, to repair & adjust chassis member.

14 To supply and apply anti rust treatment

\$	150.00	120d
Total :	\$	5,950.00

Total Parts and Labour : \$ 40,316.76

LKK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before and after spray painting and display damage for supply and apply
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: