

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111

ATTN: Motor Claim Department

FAX: 62221033

WS Ref: TP CHINA

Claim Type: Third Party

Accident Date: 16/09/2020

TP Veh Reg No: PA6538G

Estimate No: ES2090733/WS

Date: 18 Sep 2020

Policy No:

Veh Reg No: SMQ9412S

Make/Model: TOYOTA TOYOTA
 NOAH

Chassis No: ZWR800305629

Engine No:

Reg. Date: 26/07/2018

Estimate Repair Cost to Vehicle No :SMQ9412S

Description	U/Price	Quantity	List Price	Amount
Cost Plus			SS	SS
1 REAR TAILGATE	650.00	1 PC	650.00	—
2 REAR TAILGATE EMBLEM - HYBRID	35.00	1 PC	35.00	—
3 REAR TAILGATE OUTER CHROME MOULDING	310.00	1 PC	310.00	—
4 REAR WINDSCREEN GLASS	650.00	1 PC	650.00	✓
			1,645.00	1,645.00
Special Net				
5 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			40.00	40.00
Labour				
6 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
7 TO REMOVE AND REFIX TAILGATE, LOCY ASSY, REAR WIPER ASSY AND RE-ALIGN THE SAME	400.00	1 LA	400.00	✓
8 TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	50.00	1 LA	50.00	✓
9 TO PUTTY AND RESPRAY ON TAILGATE	400.00	1 LA	400.00	✓
10 RUSTPROOFING	30.00	1 LA	30.00	✓
			980.00	980.00

Total SS 2,665.00

Add GST @ 7% 186.55

Total Amount Payable SS 2,851.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE