

Not Authoite
Resurvey B4 point

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9567G

AAD2009-074

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

16 SEP 2020

SHD 9567G

JTDKB3FU503082028

TOYOTA

PRIUS

14.9.2020

CHINA TAIPING

27/06/2019

PART	
1	PANEL SUB-ASSY, FRONT DOOR, LH
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRONT LH
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH
1	TAPE, BLACK OUT, NO.1 FRT LH
1	TAPE, BLACK OUT, NO.2 FRT LH
1	TAPE, BLACK OUT, NO.3 FRT LH
1	PANEL SUB-ASSY, REAR DOOR, LH
1	TAPE, BLACK OUT, NO.1 REAR LH
1	TAPE, BLACK OUT, NO.2 REAR LH
1	TAPE, BLACK OUT, NO.3 REAR LH
1	HINGE ASSY, REAR DOOR, LOWER LH
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH
1	MOULDING ASSY, BODY ROCKER PANEL, LH
1	REINFORCE SUB-ASSY, ROCKER, OUTER LH
1	PANEL SUB-ASSY, QUARTER, LH
1	LINER, REAR WHEEL HOUSE, LH

LIST	
\$	By/way 1,300.70 ✓
\$	1 926.00 X
\$	1 238.30 X
\$	1 13.30 —
\$	1 43.50 —
\$	1 26.30 —
\$	1 1,294.90
\$	1 21.90
\$	1 34.90
\$	1 15.40
\$	1 87.10
\$	1 926.00
\$	1 206.70
\$	1 594.80
\$	1 583.40
\$	1 871.50
\$	1 139.80

TOTAL \$ 7,324.50
25% \$ 1,831.13
\$ 5,493.38

Special Nett

1	FRONT DOOR STICKER 'TRANS-CAB'
1	REAR DOOR STICKER "6555-3333"
1	WHEEL, RIM
2	WINDSCREEN SEALANT
1	WINDSCREEN MOULDING
1	WINDSCREEN INNER SPONGE SEAL

\$	1 100.00 605m
\$	1 100.00 605m
\$	1 1,879.40 X
\$	1 150.00 X
\$	1 200.00 X
\$	1 130.00 X

AAD2009-074

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9567G

- 1 REAR FENDER LINER CLIP
1 REAR BUMPER CLIP
1SET ROCKER PANEL MOULDING CLIP

\$	nn	75.00	X
\$	nn	85.00	X
\$	nn	65.00	X
TOTAL	\$	2,784.40	

TOTAL PARTS \$ 8,277.78

LABOUR

To transfer of door fittings, attachment and perform water seepage test.

\$ 300.00 601

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 5001

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 301

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 601

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 8001

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 201

To transfer of windscreen glass to facilitate bodywork repair.

\$ nn 170.00 X

TOTAL \$ 4,460.00

Over All Total \$ 12,737.78

(PART-BY-PART) Repair Days

25 days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: