


Section A - Accident Details

Registration Number	SHB5452R
Case Reference Number	TAX/09/20/2037
Registration Date	8/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YUE FOH KUM
Type of Accident	Head to Rear
Accident Date and Time	15/9/2020 2:30 PM
Accident Reported Date and Time	15/9/2020 3:39 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108164
Special Instruction to ARC, if any	FRONT AND REAR PORTION
Prepared Date and Time	16/9/2020 8:18 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,602.00	\$600.00
Total Spray Cost	\$2,394.00	\$700.00
Total Spare Part Cost	\$12,123.78	\$1,284.14
Total Other Cost	\$1,606.88	\$406.88
TOTAL COST	\$17,726.66	\$2,991.02
Lump Sum Total	\$17,750.00	\$3,000.00 (L/S)
Number of Repair Days	10.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	21/09/2020 12:08 PM	18/09/2020 12:22 PM
Signature		
Remarks	Total number of repair days = 5 days. SUP = + 2 days.	L/S, After paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2010-0015	Invoice Number	
Quotation Date	05.10.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$338.00	\$100.00
TO REPAIR REAR PORTION	\$1,014.00	\$300.00
TO REPAIR REAR END PANEL	\$250.00	\$200.00
Total Labour	\$1,602.00	\$600.00

Supp

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,394.00	\$700.00

Supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,606.88	\$406.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/10/2020

User ID : PohSuan

	52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given	X	SVC
	52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check	X	SVC
	52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	X	SVC
	57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X	SVC
	57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X	SVC
	52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace	/	BR
		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	/	CRU
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	/	CRU
	52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X	SVC
	52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X	SVC
	53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X	SVC
	81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given	X	SVC
	81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given	X	SVC
	81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X	SVC
	81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X	SVC
	53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X	SVC
	75310-47010	EMBLEM FRONT	0.00	\$86.50	0.00	\$0.00	Replace	Not Given	X	SVC
	76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X	SVC
	52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X	SVC
	52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X	SVC
	52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X	SVC
	52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	/	CRU
	52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	/	NEC
	52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X	SVC
	52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X	SVC
	52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X	SVC
	89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check	X	SVC
		SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	/	SHORT
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/	NEC
	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check	X	SVC
	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check	X	SVC
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check	X	SVC
	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X	SVC
	52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X	SVC
	52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X	SVC
	52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X	SVC
	58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X	SVC
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair	/	
	56117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	0.00	\$27.30	0.00	\$0.00	Replace	Not Given	X	SVC
	75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	SVC
	75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	SVC
	75575-47030	MOULDING BACK WINDOW, LOWER NO.1	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/10/2020

User ID : PohSuan

68294-47050	DAM, BACK DOOR GLASS ADHESIVE, NO.2	0.00	\$17.40	0.00	\$0.00	Replace	Not Given X	SVC
75575-47020	MOULDING, BACK WINDOW, LOWER NO.2	0.00	\$29.40	0.00	\$0.00	Replace	Not Given X	SVC
75574-47010	MOULDING, BACK WINDOW, OUTSIDE LH NO.2	0.00	\$29.40	0.00	\$0.00	Replace	Not Given X	SVC
75573-47090	MOULDING, BACK WINDOW, OUTSIDE RH NO.2	0.00	\$29.40	0.00	\$0.00	Replace	Not Given X	SVC
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X	SVC
68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given X	SVC
69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given X	SVC
69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given X	SVC
67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	CRU
76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given X	SVC
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given X	SVC
75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given X	SVC
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given X	SVC
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given X	SVC
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	NEC
75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given X	SVC
75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given X	SVC
76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given X	SVC
81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given X	SVC
	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X	SVC
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X	SVC
58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check X	SVC
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X	SVC
64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check X	SVC
58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check X	SVC
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X	SVC
58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Not Given X	SVC
64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given X	SVC
58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given X	SVC
58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Not Given X	SVC
64740-47031B2	PANEL ASSY, DECK LH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given X	SVC
64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given X	SVC
82161-47B22	WIRE, FLOOR	0.00	\$1,675.00	0.00	\$0.00	Replace	Not Given X	SVC
82162-47B20	WIRE, FLOOR, NO.2	0.00	\$1,305.40	0.00	\$0.00	Replace	Not Given X	SVC
Total			\$18,065.82		\$1,069.81			

605.17 ✓
- 20 Z
287.14 ✓
+ 600.00 ✓
106.58 ✓
991.02 ✓
45 \$3000 ✓

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace
Total					713.80		535.36		

5 days
/BT
/BT
/BT
/CRU