

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12  
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

**INSURER :**

| <b>PARTICULARS OF CLAIM</b> |                       |                              |                       |
|-----------------------------|-----------------------|------------------------------|-----------------------|
| Claim Type:                 | TP                    | Ref. No:                     | YTMG/TP/2009/004      |
| Policy No:                  | 5069479433-05         | Date of Loss:                | 25/08/2020            |
| Vehicle Reg. No.:           | <b>FBJ1788C</b>       | Driveable?                   | yes                   |
| Driver Age:                 | 07/01/1957            | Third Party Vehicle No.:     | SHA7828H              |
| Any Injuries?               | yes                   | Contact No:                  | 92476945              |
| Insured/Claimant:           | MD ARIF BIN DJARIDJAN | Driver:                      | MD ARIF BIN DJARIDJAN |
| <hr/>                       |                       |                              |                       |
| Make/Model:                 | Yamaha, Jupiter       | Vehicle Reg. Date:           | 23/01/2014            |
| Vehicle Colour:             | Blue                  | Engine Number:               | 50C658525             |
| Chassis No:                 | MH350C004DK658355     | Odometer:                    |                       |
| Total Loss?                 |                       | Est. Duration of Repair(Day) |                       |

Description of Accident/loss COLLISION - U-TURN  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

| <b>COST OF CLAIMS</b>    | <b>Amount</b>   |
|--------------------------|-----------------|
| Parts                    | 5,074.20        |
| Miscellaneous Items      | 165.00          |
| Labour                   | 2,590.00        |
| Paintwork Labour         | 490.00          |
| Towing                   | 0.00            |
| <b>Gross Total(S\$):</b> | <b>8,319.20</b> |
| <b>GST 7.00%(S\$):</b>   | <b>582.34</b>   |
| <b>Nett Amount(S\$):</b> | <b>8,901.54</b> |

This claim is handled by: Sky Toh T C

**REPAIR DETAILS****Estimates On Parts**

| No. | Qty | Particulars                                         | Amount | %Disc  | After Disc |
|-----|-----|-----------------------------------------------------|--------|--------|------------|
| 1   | 1   | FRONT FENDER / <del>CRU</del> SCR                   | 155.00 | -10.00 | 139.50     |
| 2   | 1   | FRONT FORK LH ?                                     | 190.00 | -10.00 | 171.00     |
| 3   | 1   | FRONT FORK RH ?                                     | 190.00 | -10.00 | 171.00     |
| 4   | 1   | FRONT WHEEL DISC ROTOR RH X NN                      | 170.00 | -10.00 | 153.00     |
| 5   | 1   | FRONT BRAKE CALIPER RH X NN                         | 230.00 | -10.00 | 207.00     |
| 6   | 1   | FRONT FAIRING / SCR                                 | 380.00 | -10.00 | 342.00     |
| 7   | 1   | FRONT FAIRING SIDE LAMP RH                          | 310.00 | -10.00 | 279.00     |
| 8   | 1   | FRONT FAIRING INNER FAIRING / CRU.                  | 390.00 | -10.00 | 351.00     |
| 9   | 1   | FRONT FAIRING LOWER FAIRING / CRU                   | 220.00 | -10.00 | 198.00     |
| 10  | 1   | FRONT HEADLAMP X NN                                 | 377.00 | -10.00 | 339.30     |
| 11  | 1   | FRONT HEADLAMP FAIRING / SCR                        | 330.00 | -10.00 | 297.00     |
| 12  | 1   | FRONT HEADLAMP BRACKET X NN                         | 55.00  | -10.00 | 49.50      |
| 13  | 1   | FRONT BRAKE LEVER RH / BT                           | 35.00  | -10.00 | 31.50      |
| 14  | 1   | FRONT BALANCER RH / SCR                             | 12.00  | -10.00 | 10.80      |
| 15  | 1   | FRONT SIDE MIRROR RH / SCR                          | 65.00  | -10.00 | 58.50      |
| 16  | 1   | FRONT STEERING STEM ?                               | 135.00 | -10.00 | 121.50     |
| 17  | 1   | FRONT STEERING CONE & BEARING ?                     | 95.00  | -10.00 | 85.50      |
| 18  | 1   | FRONT SIDE FAIRING RH / MJS                         | 380.00 | -10.00 | 342.00     |
| 19  | 1   | FRONT SIDE INNER FAIRING RH / MJS                   | 177.00 | -10.00 | 159.30     |
| 20  | 1   | FRONT SIDE FAIRING LOGO RH / NEC                    | 55.00  | -10.00 | 49.50      |
| 21  | 1   | RADIATOR / CRU.                                     | 477.00 | -10.00 | 429.30     |
| 22  | 1   | RADIATOR BRACKET ?                                  | 55.00  | -10.00 | 49.50      |
| 23  | 1   | FRONT LOWER CENTRE COVER / CRU                      | 110.00 | -10.00 | 99.00      |
| 24  | 1   | ENGINE COVER RH / EBR                               | 240.00 | -10.00 | 216.00     |
| 25  | 1   | ENGINE GASKET / NEC                                 | 55.00  | -10.00 | 49.50      |
| 26  | 1   | FRONT FOOT BRAKE RH / BT                            | 35.00  | -10.00 | 31.50      |
| 27  | 1   | FRONT SIDE CENTRE GARNISH RH ?                      | 130.00 | -10.00 | 117.00     |
| 28  | 1   | REAR FAIRING RH / CRU                               | 330.00 | -10.00 | 297.00     |
| 29  | 1   | REAR FAIRING LOGO RH / NEC                          | 55.00  | -10.00 | 49.50      |
| 30  | 1   | REAR FOOT REST RH / SCR                             | 35.00  | -10.00 | 31.50      |
| 31  | 1   | REAR EXHAUST SILENCER CHROME / SCR.<br>PROTECTOR RH | 165.00 | -10.00 | 148.50     |

Total Parts (\$\$) 5,074.20

**Estimates of Miscellaneous Items**

| No. | Qty | Particulars         | Amount | %Disc | After Disc |
|-----|-----|---------------------|--------|-------|------------|
| 1   | 1   | CENTRE BASKET / CRU | 90.00  | 0.00  | 90.00      |
| 2   | 1   | ENGINE OIL / NEC    | 75.00  | 0.00  | 75.00      |

Sub Total (\$\$) 165.00

**Estimates On Labour**

| No. | Qty | Particulars                                                                                         | Amount   | %Disc | After Disc    |
|-----|-----|-----------------------------------------------------------------------------------------------------|----------|-------|---------------|
| 1   | 1   | To Supply Labour To Overhaul Engine.                                                                | 1,200.00 | 0.00  | 1,200.00 150? |
| 2   | 1   | To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings. | 180.00   | 0.00  | 180.00 30     |
| 3   | 1   | To Dismantle and Refit Front Undercarriage.                                                         | 220.00   | 0.00  | 220.00 X      |
| 4   | 1   | To Disconnect and Reconnect, Check Electrical                                                       | 30.00    | 0.00  | 30.00 /       |

**Estimates On Labour**

| No. | Qty | Particulars                                                                                                                                                                           | Amount                         | %Disc | After Disc      |
|-----|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------|-----------------|
|     |     | wiring Harness Wire, Sockets, Replace Damaged Parts.                                                                                                                                  |                                |       |                 |
| 5   | 1   | To Conduct Wheel Balancing                                                                                                                                                            | 60.00                          | 0.00  | 60.00 X         |
| 6   | 1   | To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools. | 900.00                         | 0.00  | 900.00<br>250   |
|     |     |                                                                                                                                                                                       | <b>Gross Labour Cost (S\$)</b> |       | <b>2,590.00</b> |

**Estimates On Paint Work Labour**

| No. | Qty | Particulars                                                                                                                                                                                              | Amount                         | %Disc | After Disc    |
|-----|-----|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------|---------------|
| 1   | 1   | To Carry-Out Body Cavity Preservation.                                                                                                                                                                   | 40.00                          | 0.00  | 40.00 X       |
| 2   | 1   | To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available. | 450.00                         | 0.00  | 450.00 X      |
|     |     |                                                                                                                                                                                                          | <b>Gross Labour Cost (S\$)</b> |       | <b>490.00</b> |

**< END OF ESTIMATES >**

Repair dy - 3 days

4/5

After paint photo

Sim Pin (Lide)

16/09/2020

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: