



Repair Estimate

VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Steve (LK)K
8322 8813
Steve Chen@1KKAuto.com

WHL ML
21/9/20, 4.00pm
3 days
L/S, R/L ML SJ

Date : 16-Sep-2020

Vehicle Num : SJY1957H

Make/Model : Lexus GS300

Chassis No : JTHBH1965205068526

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear Bumper <i>BR</i>	1	\$ 540.00	\$ 540.00
2	RH Tow-eye Cap <i>X NM</i>	1	\$ 27.00	\$ 27.00
3	Absorber, Rear Bumper <i>BR</i>	1	\$ 117.00	\$ 117.00
4	Reinforcement <i>BT</i>	1	\$ 324.00	\$ 324.00
5	RH Support, Rear Bumper <i>BR</i>	1	\$ 72.00	\$ 72.00
6	LH Support, Rear Bumper <i>BR</i>	1	\$ 72.00	\$ 72.00
7	RH Top Retainer, Rear Bumper <i>X NM</i>	1	\$ 49.00	\$ 49.00
8	LH Top Retainer, Rear Bumper <i>X NM</i>	1	\$ 54.00	\$ 54.00
TOTAL PARTS				\$ 1,255.00
Less 25%				\$ 313.75
TOTAL AMOUNT				\$ 941.25
MISCELLANEOUS ITEM				
1	Sunderies <i>APC</i>		\$ 25.00	\$ 25.00
2	Reverse Sensors		\$ 200.00	\$ 200.00
LABOUR				
1	Remove and refit Rear Bumper, Reinforcement, supports, Retainers and other associated components.		\$ 250 400.00	\$ 400.00
2	Surface preparation, spray paint and polish Rear bumper, Reverse sensors and other affected areas.		\$ 400 500.00	\$ 500.00
3	Remove and refit Reverse sensors to assist the repair.		\$ 20.00	\$ 20.00
4	Diagnostic check and erase fault codes.		\$ 30 80.00	\$ 80.00
TOTAL				\$ 2,166.25
GST 7%				\$ 151.64
GRAND TOTAL				\$ 2,317.89

1125
-25%
843.75

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-843.75
N-25
L-700
1568.75

L/S - 1255
= 1250