

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG20010034/ARS3Q2

Date:

27/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800135651

Claimant Vehicle No : GBC7700C

Insured Vehicle No :

SJN4516K

Date of Loss: 14/09/2020

Nature of Claim:

TP

Claim No:

2769008538SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC7700C**

Make & Model: NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A)

Engine No:

ZD30274629K

Reg. Date: 28/05/2011 (Man. Year: 2010)

Chassis No:

JN1MG4E25Z0794889

Colour: Silver

Odometer:

305796 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: OHTSU 6 mm

Rear Left Side:

OHTSU 6 mm

Front Right Side: OHTSU 6 mm

Rear Right Side:

OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,825.82	1,714.46	5,111.36	74.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,800.00	1,670.00	48.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,295.82	3,514.46	6,781.36	65.87
Approved Total (Overridden) (S\$)		2,800.00		

(S\$)	10,295.82	2,800.00	7,495.82	72.80
+ GST 7.00/7.00% (S\$)	720.71	196.00	524.71	72.80
Nett Amount (S\$)	11,016.53	2,996.00	8,020.53	72.80
+ Loss of Use (6.0 x S\$90.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,538.00		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment: 17/09/2020

Date Inspected: 17/09/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	660.00 FN	*660.00 FN
2	2		*REAR BUMPER SIDE CLIPS	Necessary	40.80 FN	*40.80 FN
3	1		*REAR LH VENTILATION AIRDUCT	Deformed	66.00 FN	*66.00 FN
4	2		*REAR BUMPER BRACKET	Not Necessary	338.00 FN	*- FN
5	1		*BOOT LID	Repair	1,916.20 FN	*- FN
6	1		*BOOT LID URVAN STICKER	Necessary	21.40 FN	*21.40 FN
7	1		*BOOT LID LOGO	Necessary	60.00 FN	*60.00 FN
8	1		*BOOT LID 3.0 DTI STICKER	Necessary	21.40 FN	*21.40 FN
9	1		*BOOT LID RUBBER	Not Necessary	180.80 FN	*- FN
10	1		*EXHAUST PIPE	Repair	830.00 FN	*- FN
11	2		*EXHAUST PIPE MOUNTING	Not Necessary	55.40 FN	*- FN
12	1		*TAIL LAMP LH	Cracked	230.80 FN	*230.80 FN
13	1		*REAR FENDER	Repair	2,170.00 FN	*- FN
14	1		*END PAEL	Dented	549.00 FN	*549.00 FN
15	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
16	1		*BOOTLID 9 PAX STICKER	Necessary	15.00 FS	*15.00 FS
17	1		*BOOTLID 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
18	1		*REAR WINDSCREEN SEAL	Not Necessary	60.00 FS	*- FS
19	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	7,539.80	1,879.40
- Nett Item Discount on N Items 10.00/10.00% (\$)	713.98	164.94
Total Parts (\$)	6,825.82	1,714.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	0.00
3	TO REMOVE AND REFIT BOOTLID TRIM	New	100.00	0.00
4	TO REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	80.00
5	TO REMOVE AND REFIX REVERSE SENSOR	New	100.00	50.00
6	TO SPRAY UNDERSEAL	New	150.00	40.00
7	(REAR)TO SPRAY PAINTING	New	1,200.00	800.00
8	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS	New	1,600.00	800.00
Gross Labour Cost (\$\$)			3,470.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >