

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

*Liberty
clean*

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST2000190**
Date: 15 Sep 2020
Veh Reg No: **GBC7700C**
Make/Model: NISSAN URVAN 3.0
5MT ABS AB 5DR LWB
PANEL
Chasis No: JN1MG4E25Z0794889
Reg. Date: 28/05/2011
Your Ref No: SJN4516X

Claim Type: Third Party
Accident Date: 14/09/2020
TP Veh Reg No: SJN4516X

Suslin

Estimate Repair Cost to Vehicle No :GBC7700C

Quantity	Description	List Price	Amount
		SS	SS
	Net Price		
1	1 PC REAR BUMPER <i>Rehd</i>	660.00	✓
2	2 PCS REAR BUMPER SIDE CLIPS <i>new</i>	40.80	✓
3	1 PC REAR LH VENTILATION AIRDUCT <i>Rehd</i>	66.00	✓
4	2 PCS REAR BUMPER BRACKET <i>Rehd</i>	338.00	✓
5	1 PC BOOT LID <i>Rehd</i>	1,916.20	✓
6	1 PC BOOT LID "URVAN" STICKER <i>new</i>	21.40	✓
7	1 PC BOOT LID LOGO <i>new</i>	60.00	✓
8	1 PC BOOT LID "3.0 DTI" STICKER <i>new</i>	21.40	✓
9	1 PC BOOT LID RUBBER <i>new</i>	180.80	✓
10	1 PC EXHAUST PIPE <i>Rehd</i>	830.00	✓
11	2 PCS EXHAUST PIPE MOUNTING <i>new</i>	55.40	✓
12	1 PC TAIL LAMP LH <i>Rehd</i>	230.80	✓
13	1 PC REAR FENDER <i>Rehd</i>	2,170.00	✓
	End Panel <i>Rehd</i> ✓ 549.	6,590.80	
	Less 10%	659.08	5,931.72
	Special Net		
14	1 SET REVERSE SENSORS <i>Rehd</i>	250.00	20
15	1 PC BOOTLID "9 PAX" STICKER <i>new</i>	15.00	✓
16	1 PC BOOTLID "70KM/H" STICKER <i>new</i>	15.00	✓
17	1 PC REAR WINDSCREEN SEAL <i>new</i>	60.00	✓
18	1 PC REAR WINDSCREEN SEALANT <i>new</i>	60.00	✓
		400.00	400.00
	Labour		
19	1 TO CHECK WIRING	50.00	30
20	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
21	1 TO REMOVE AND REFIT BOOTLID TRIM	100.00	✓
22	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00	80
23	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00	50

1649.40

1484.46

230

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

ASIA PACIFIC INSURANCE PTE LTD
SHENTON WAY #07-16
G BUILDING, SINGAPORE 079120
193000 FAX: 68357416
Motor Claim Department

e: Third Party
Date: 14/09/2020
eg No: SJN4516X

Estimate No: EST2000190
Date: 15 Sep 2020
Veh Reg No: GBC7700C
Make/Model: NISSAN URVAN 3.0
5MT ABS AB 5DR LWB
PANEL
Chasis No: JN1MG4E25Z0794889
Reg. Date: 28/05/2011
Your Ref No: SJN4516X

Estimate Repair Cost to Vehicle No :GBC7700C

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
1	TO SPRAY UNDERSEAL	1800	150.00 40
1	(REAR) TO SPRAY PAINTING		1,200.00 800
1	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.		1,600.00 800
		3,470.00	3,470.00
	Total		S\$ 9,801.72
	Add GST @ 7%		686.12
	Total Amount Payable		<u>S\$ 10,487.84</u>

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FOUR HUNDRED EIGHTY SEVEN AND CENTS
EIGHTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Adrian Lj total: 351446
1/s 17/09/20 1/s: 28k
05 Days. 2.8k