



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2105298

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 29/07/2021
Reference CC4/FCI20010037/Drs3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 4097P
Insured Veh. SHC 2729H
Claim No. D20003740MFSH
Policy No. D-20094922MFSH
Accident Date 14/09/2020
Inspection Date 18/09/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010037/Drs3q2	
			Date: 29/07/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2729H	Veh. Inspected	SHB 4097P	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20003740MFSH	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	18/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU080355	Colour	BLUE	
Odometer	628483 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	DURATURN	5 mm	
L/H Front Tyre	205/60 R16	DURATURN	5 mm	
R/H Rear Tyre	205/60 R16	DURATURN	5 mm	
L/H Rear Tyre	205/60 R16	DURATURN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/09/2020	Inspection Date	18/09/2020	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4097P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER (LH)	TO REPAIR SEE LABOUR	2,171.40	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	51.80	-
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	ROCKER PANEL OUTER GARNISH (LH)	CUT	732.80	483.60
1	FRONT BUMPER COVER	DENTED	1,052.20	1,052.20
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$44.80	NOT NECESSARY	89.60	-
2	FRONT BUMPER BRACKET (LH/RH) @\$49.20	NOT NECESSARY	98.40	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	MTG BROKEN	2,776.00	1,388.00
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	TO REPAIR SEE LABOUR	637.00	-
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	174.90	-
1	FRONT DOOR MIRROR SIDE GARNISH	NOT NECESSARY	225.00	-
1	FRONT DOOR (LH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR RUBBER	SERVICEABLE	196.00	-
1	FRONT DOOR HINGE UPPER (LH)	NOT NECESSARY	113.60	-
1	FRONT DOOR HINGE LOWER (LH)	NOT NECESSARY	125.70	-
1	FRONT DOOR LOCK (LH)	NOT NECESSARY	91.80	-
1	DOOR CENTRE PILLAR OUTER (LH)	NOT NECESSARY	2,527.80	-
1	FRONT WHEEL RIM (LH)	DISTORTED	650.60	325.30
1	KNUCKLE ARM (LH)	DISTORTED	595.90	595.90
1	FRONT WHEEL BEARING HUB ASSY (LH)	DAMAGED	673.20	301.80
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	1,104.00	529.30
1	FRONT SHOCK ABSORBER ASSY (LH)	DISTORTED	684.40	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	217.60	-
1	STG TIE ROD (LH)	DISTORTED	186.40	186.40
1	STG TIE END (LH)	DISTORTED	125.20	125.20
1	STABILIZER BAR ASSY	NOT NECESSARY	463.70	-

Report Ref No. CC4/FCI20010037/Drs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STABILIZER BAR LINK (LH)	NOT NECESSARY	68.10	-
1	ABS SENSOR	NOT NECESSARY	217.90	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	2,061.60	-
1	RACK & PINION ASSY	NOT NECESSARY	1,820.00	-
1	REAR TYRE RIM (LH) (ADDITIONAL)	DISTORTED	650.60	325.30
1	REAR TYRE WHEEL CAP (LH) (ADDITIONAL)	CUT	214.20	107.10
1	REAR WHEEL BEARING & HUB ASSY (LH) (ADDITIONAL)	DAMAGED	724.00	362.00
1	REAR SHOCK ABSORBER (LH) (ADDITIONAL)	DISTORTED	683.70	341.80
1	REAR UPPER ARM (LH) (ADDITIONAL)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH) (ADDITIONAL)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH) (ADDITIONAL)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-5,918.81	-2,726.49
			23,675.24	10,905.96
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMOFORT LOGO (SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			417.00	155.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER (LH) AND FRONT FENDER APRON PANEL (LH).		1,400.00	900.00
	SPRAY PAINTING CHARGE.		1,200.00	900.00
	WIRING CHARGE.		160.00	30.00
	TUFF KOTE.		140.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR .	NOT NECESSARY	150.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS .	NOT NECESSARY	120.00	-
	TRANSFER OF DOOR MECHANISM FRONT .		80.00	60.00
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	TRANSFER OF DOOR MECHANISM REAR .		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-

Report Ref No. CC4/FCI20010037/Drs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	FOUR WHEEL ALIGNMENT .	NOT NECESSARY	120.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	RE-SET FRT ABS SYSTEM.		200.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			5,080.00	2,350.00
GRAND TOTAL			29,172.24	13,410.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,700.00

Report Ref No. CC4/FCI20010037/Drs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 4097P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 4097P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 4097P

RE-INSPECTION

