

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 14-Sep-20

INSURANCE: First Capital

MODEL: HYUNDAI I40


VEHICLE NO.: SHB 4097 P

CC4/FCI 20010037 Drs<sup>3</sup>

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR FENDER (LH) <i>ray</i>	1	\$2,171.40	\$2,171.40	X
REAR WINDSCREEN MOULDING <i>HH</i>	1	\$51.80	\$51.80	X
REAR DOOR (LH) <i>Dented</i>	1	\$2,201.10	\$2,201.10	✓
ROCKER PANEL OUTER GARNISH (LH) <i>cut 483.60</i>	1	<del>\$732.80</del>	<del>\$732.80</del>	✓
FRONT BUMPER COVER <i>Dented</i>	1	\$1,052.20	\$1,052.20	✓
FRONT BUMPER BRACKET TOP (LH/RH) <i>HH</i>	2	\$44.80	\$89.60	X
FRONT BUMPER BRACKET (LH/RH) <i>HH</i>	2	\$49.20	\$98.40	X
HEADLAMP SUPPORT PANEL ASSY <i>2 broken</i>	1	\$907.40	\$907.40	✓
HEADLAMP (LH) <i>mainly broken 1388.00</i>	1	<del>\$2,776.00</del>	<del>\$2,776.00</del>	X
HEADLAMP SUPPORT TOP COVER <i>HH</i>	1	\$222.60	\$222.60	✓
FRONT FENDER (LH) <i>Dented</i>	1	\$566.30	\$566.30	✓
FRONT FENDER APRON PANEL (LH) <i>HH ray</i>	1	\$637.00	\$637.00	X
FRONT FENDER SHIELD (LH) <i>2 str</i>	1	\$174.90	\$174.90	✓
FRONT DOOR MIRROR SIDE GARNISH <i>HH</i>	1	\$225.00	\$225.00	X
FRONT DOOR (LH) <i>Dented</i>	1	\$2,256.40	\$2,256.40	✓
FRONT DOOR RUBBER <i>str</i>	1	\$196.00	\$196.00	X
FRONT DOOR HINGE UPPER (LH) <i>2 HH</i>	1	\$113.60	\$113.60	✓
FRONT DOOR HINGE LOWER (LH) <i>HH</i>	1	\$125.70	\$125.70	X
FRONT DOOR CHECK (LH) <i>HH</i>	1	\$91.80	\$91.80	X
DOOR CENTRE PILLAR OUTER (LH) <i>HH</i>	1	\$2,527.80	\$2,527.80	✓
FRONT WHEEL RIM (LH) <i>2 distal 325.30</i>	1	<del>\$650.60</del>	<del>\$650.60</del>	✓
KNUCKLE ARM (LH) <i>2 distal</i>	1	\$595.90	\$595.90	✓
FRONT WHEEL BEARING HUB ASSY (LH) <i>2 D.M</i>	301.801	\$673.20	\$673.20	✓
FRONT SUSPENSION LOWER ARM (LH) <i>2 distal</i>	529.301	\$1,104.00	\$1,104.00	✓
FRONT SHOCK ABSORBER ASSY (LH) <i>2 distal</i>	342.201	<del>\$684.40</del>	<del>\$684.40</del>	✓
FRONT SHOCK ABSORBER MOUNTING (LH) <i>HH</i>	1	\$217.60	\$217.60	X
STG TIE ROD (LH) <i>2 distal</i>	1	\$186.40	\$186.40	✓
STG TIE END (LH) <i>2 distal</i>	1	\$125.20	\$125.20	✓
STABILIZER BAR ASSY <i>HH</i>	1	\$463.70	\$463.70	X
STABILIZER BAR LINK (LH) <i>HH</i>	1	\$68.10	\$68.10	X
ABS SENSOR <i>HH</i>	1	\$217.90	\$217.90	X
FRONT DRIVE SHAFT (LH) <i>HH</i>	1	\$2,061.60	\$2,061.60	X
RACK & PINION ASSY <i>HH</i>	1	\$1,820.00	\$1,820.00	X
<b>SUB TOTAL</b> <i>11261.10</i>			<b>\$26,086.40</b>	
<b>LESS 20%</b>			<b>\$5,217.28</b>	
<b>DISCOUNTED TOTAL</b> <i>9008.88</i>			<b>\$20,869.12</b>	
REAR WINDSCREEN SEALANT <i>HH</i> SN	1	\$46.00	\$46.00	X
Rear Door Comfortdelgro & Apps Sticker(LH) <i>HH</i> SN	1	\$ 80.00	\$ 80.00	✓
FRONT DOOR COLOURED COMFORT LOGO <i>HH</i> SN	1	\$75.00	\$75.00	✓
FRONT TYRE (LH) <i>HH</i> SN	1	\$216.00	\$216.00	X
<i>155.00</i>				

<b>SUB TOTAL</b>			<b>\$417.00</b>	
<b>Labour Charge</b>				
Panel Beating	1	\$1,400.00	\$1,400.00	900/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	900/-
Wiring Charge	1	\$160.00	\$160.00	30/-
Tuff Kote	1	\$140.00	\$140.00	40/-
Towing Charge	1	\$80.00	\$80.00	40/-
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	40/-
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$120.00	40/-
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$200.00	\$200.00	40/-
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$200.00	\$200.00	40/-
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	150/-
Re-set Frt ABS System	1	\$200.00	\$200.00	40/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
<b>TOTAL LABOUR</b>			<b>\$5,080.00</b>	
<b>ESTIMATE TOTAL</b>			<b>\$ 26,366.12</b>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

18/09/2020 @ 1730hrs  
 Not Actual  
 2/sum 9 dgs.



LKK Auto



11513.88  
 SUPP 1897.08  
 13410.96  
 4/s 10700/-

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# BIFROST AUTO PTE LTD

## REPAIR SUPPLEMENTARY

DATE: 21-Sep-20

INSURANCE: First Capital

MODEL: HYUNDAI I40

VEHICLE NO.: SHB 4097 P (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TYRE RIM (LH) <i>distorted</i> 325.30	1	\$650.60	\$650.60
REAR TYRE WHEEL CAP (LH) <i>cut</i> 107.10	1	\$214.20	\$214.20
REAR WHEEL BEARING & HUB ASSY (LH) <i>Done</i> 362.00	1	\$724.00	\$724.00
REAR SHOCK ABSORBER (LH) <i>distorted</i> 341.80	1	\$683.70	\$683.70
REAR UPPER ARM (LH) <i>distorted</i>	1	\$335.75	\$335.75
REAR LOWER ARM (LH) <i>distorted</i>	1	\$353.80	\$353.80
REAR KNUCKLE ARM (LH) <i>distorted</i>	1	\$545.60	\$545.60
<b>SUB TOTAL</b>			<b>\$3,507.65</b>
<b>LESS 20%</b>			<b>\$701.53</b>
<b>DISCOUNTED TOTAL</b>			<b>\$2,806.12</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

21/09/20 20980km

aka Arthur

1/10/20

*[Signature]*

mya

2KK Auto

2371.35

1897.08

*[Large Signature]*