



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2102379

INV Date 09/04/2021

Reference CC4/FCI20010038/Kes3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 3530L

Insured Veh. SHC 1687B

Claim No. D20003780MFSH

Policy No. D-20094922MFSH

Accident Date 15/09/2020

Inspection Date 22/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010038/Kes3q2	
			Date: 09/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1687B	Veh. Inspected	GBF 3530L	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20003780MFSH	Excess (\$)	0.00	
Assign From	CHRIS LIM	Assign Date	18/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFHT02P100203619	Colour	WHITE	
Odometer	144301 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	8 mm	
L/H Front Tyre	195 R15X8	MICHELIN	8 mm	
R/H Rear Tyre	195 R15X8	MICHELIN	4 mm	
L/H Rear Tyre	195 R15X8	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/09/2020	Inspection Date	22/09/2020	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3530L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILAMP LH	CRACKED	306.40	306.40
1	TAILAMP LOWER COVER LH	DENTED	93.20	93.20
1	REAR BUMPER	TO REPAIR SEE LABOUR	454.30	-
	LESS 25% DISCOUNT		-213.48	-99.90
			640.42	299.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR FENDER COMPANY STICKER (SN)	NECESSARY	300.00	250.00
			300.00	250.00
	<u>LABOUR</u>			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING .		40.00	20.00
	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME .INCLUSIVE OF THE REPAIR OF REAR BUMPER .		500.00	350.00
	TO SPRAY REAR BUMPER ,REAR FENDER LH ,TAILAMP LOWER COVER LH .		600.00	500.00
			1,140.00	870.00
	GRAND TOTAL		2,080.42	1,419.70
	RECOMMENDED COST OF REPAIRS			1,419.70

Report Ref No. CC4/FCI20010038/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 3530L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 3530L

RE-INSPECTION

