

TOTAL

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

LKK ASIA

Not Authorized
here
2/4/20 4500/
21/9/20
5 days.

E No: SJS 5373Y

BOOTLID 907.20
BOOTLID 'H' LOGO
BOOTLID 'AVANTE' EMBLEM 42.50
BOOTLID 'S' EMBLEM 35.00
BOOTLID REFLECTORS @\$450.00
BOOTLID INNER LOCK
BOOTLID WEATHERSTRIP 188.20
REAR BUMPER 488.90
REAR BUMPER LOWER GARNISH
REAR BUMPER SIDE RETAINERS @\$105.00
REAR BUMPER SPONGE
REAR BUMPER REINFORCEMENT 354.00
REAR BUMPER REINFORCEMENT BRACKETS @\$165.00
REAR BUMPER REINFORCEMENT LOW & TOP BRACKETS @\$25.00
TAILLAMPS @\$981.00 300.50
REAR END PANEL 637.90
REAR END PANEL TOP GARNISH 185.60
REAR FLOOR PANEL TOP BOARD 366.50
REAR FLOOR PANEL

DD/Bent \$1,280.20
nel \$48.50
nel \$62.00
nel \$65.00
11 \$900.00 X
SVC \$215.00 X
TWI \$288.00
de \$788.50
NX \$452.00 X
11 \$210.00 X
T.M. \$188.00
CNC \$495.00
BMP \$330.00
tw/cnc \$125.00
n/sene \$1,962.00 12C
Body m \$666.00
TWI \$215.00
wepub \$499.00
R \$1,450.00 X
\$10,239.20

207

S.NETT
REAR BUMPER REVERSE SENSOR
REAR BUMPER CLIPS
REAR END PANEL SEALANT

Torn / should 280.00 200
nel \$50.00 ✓
nel \$50.00 ✓

TO CHECK WIRING
TO DISMANTLE & REPLACED REVERSE SENSOR
TO TRANSFER BOOTLID MECHANISM
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 30
\$80.00 50
\$80.00 60
\$120.00 80
\$100.00 60
\$1,200.00 680
\$1,500.00 1050
TOTAL \$13,749.20

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-4196.1
207
3356.88
5666.88