#### AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

## ASSESSMENT REPORT FOR VEHICLE NO. SME 7147 J

## PARTS (LIST ITEMS)

1 71113	, (clot it clins)		Workshop's	Our
Qty	Description	Condition		Assessment
1	FRONT BONNET XNN	Repair	1,740.70	-
2	FRONT BONNET SIDE GUIDE RUBEBR STOPPER L/R X nn	Reuse	30.00	-
1	FRONT BONNET MECHANISM LOCK X nn	Bent	129.90	129.90
1	FRONT GRILLE	Cracked	460.20	460.20
1	FRONT GRILLE 'LOGO' EMBLEM	Necessary	52.40	52.40
<b>1pc</b> 2	front headlamp L/r @1198	Cracked	<b>1198 2</b> ,396.00	2,396.00
2	FRONT HEADLAMP LOWER BRACKET L/R XNN	Bent	148.20	148.20
1	FRONT BUMPER	Cracked	528.60	528.60
1	FRONT BUMPER INNER SPONGE	Cracked	117.10	117.1(
2	FRONT BUMPER SIDE RETAINER L/R XNN	Bent	84.20	84.20
1	FRONT BUMPER UPPER COVER XNN	Cracked	92.50	92.50
1	FRONT BUMPER UPPER SEAL RUBBER XNN	Necessary	47.20	47.20
1	FRONT BUMPER NUMBER PLATE BRACKET GARNISH	Cracked	38.00	
2	FRONT BUMPER SIDE GARNISH L/R <b>xnn</b>	Cracked	268.40	268.40
1	FRONT BUMPER REINFORCEMENT repair x	Bent	695.80	695.80
1	FRONT BUMPER TOW HOOK COVER	Cracked	29.00	
1	FRONT BUMPER LOWER LID GARNISH XNN	Cracked	272.50	272.50
1	FRONT SUPPORT PANEL XNN	Repair	949.30	-
2	FRONT SUPPORT PANEL AIR GUIDE GARNISH L/R XSVC	Cracked	98.20	98.20
1	REAR BOOTLID <b>X nn</b>	Repair	1,782.00	-
2	REAR BOOTLID REFLECTOR L/R XNN	Repair	1,328.00	-
2	REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R XNN	Reuse	76.00	-
1	REAR BOOTLID LOCK STRIKER XNN	Bent	28.60	28.60
1	REAR BOOTLID MECHANISM LOCK <b>XNN</b>	Bent	161.00	161.00
1	REAR BOOTLID WEATHER STRIP <b>XNN</b>	Repair	115.00	-
2	REAR TAILLAMP L/R <b>XNN</b>	Cracked	1,752.00	1,752.00
1	REAR BUMPER	Cracked	560.40	
7.	REAR BUMPER TOP BRACKET L/R XNN	Bent	96.00	96.00
1	REAR BUMPER REINFORCEMENT	Cracked	330.00	
1pc 2	REAR BUMPER SIDE RETAINER L/R @43.30 (rh)	Bent	<b>43.30 /</b> 88.60	88.60
2	REAR BUMPER REFLECTOR L/R <b>x nn</b>	Cracked	196.00	196.00
1	REAR BUMPER LOWER LID	Cracked	335.10	
1	REAR END PANEL INNER TOP GARNISH XNN	Cut	69.80	69.80
1	REAR END PANEL <b>XNN</b>	Repair	580.00	-
1	REAR FLOOR PANEL TOP BOARD COVER XNN	Repair	498.70	
	3692.10		16,175.40	9,075.70
	20%	Less 20% discount	3,235.08	1,815.14
	2953.68	Parts Total:	12,940.32	7,260.56

#### AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

# ASSESSMENT REPORT FOR VEHICLE NO. SME 7147 J

### SPECIAL NETT ITEMS

1	FRONT GRILLE CLIPS - SET <b>nec</b>	Necessary	40.00 <b>20</b>	40.00
1	FRONT BUMPER UPPER COVER CLIPS - SET <b>XNN</b>	Necessary	50.00 <b>X</b>	50.00
1	FRONT BUMPER CLIPS - SET nec	Necessary	50.00 30 -	50.00
1	FRONT BUMPER NUMBER PLATE bt	Bent	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER Cra	Cracked	50.00	50.00
1	REAR BOOTLID INNER TRIM BOARD CLIPS - SET XNN	Necessary	50.00 <b>X</b>	50.00
2	REAR TAILLAMP CLIPS L/R - SET xnn	Necessary	100.00 <b>X</b>	100.00
1	REAR BUMPER CLIPS - SET nec	Necessary	100.00 50-	100.00
1	REAR BUMPER REVERSE SENSOR - SET <b>nw</b>	Cracked	350.00 <b>200</b>	350.00
1	REAR END PANEL INNER TOP GARNISH CLIPS - SET XNN	Necessary	50.00 <b>X</b>	50.00
	375	Special Nett Total :	865.00	865.0

#### LABOUR

S/N		Workshop's Estimate		Our
	The state of the s	130.00	60	120.0
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.		107.070	
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	100.00		80.0
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.  To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-	1,200.00	400	1,100.0
4	align body structure, body alignments and damaged consistent to the accident.  960	1,600.00		
5	To apply anti-rust chemical on repaired and replaced panel.	120.00	5.5	100.0
	Labour Total : _ TOTAL (PARTS & LABOUR) \$ _	3,150.00 16,955.32		1,025.5

2953.68

The workshop has agreed to undertake the repair o	n a Lump Sum basis. 375.00	7
The final adjusted Lump Sum contract amount is	060.00	
\$9,200.00 (SINGAPORE DOLLARS	S NINE THOUSAND TWO HUNDRED UNLY)	
	4288.68	}
	20%	
So concurs	3430.94	1
1-15-01 131	L/S - 3,4	00
	5 days	5

Amas Ong Automobile Assessor