

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2000193
Date: 16 Sep 2020
Veh Reg No: SMP4249K
Make/Model: M.BENZ CLA180 (R18 BI SR)
Chasis No: WDD1173422N190142
Reg. Date: 18/06/2015
Your Ref No: ES9120T

Claim Type: Third Party
Accident Date: 15/09/2020
TP Veh Reg No: ES9120T

Veron.

Estimate Repair Cost to Vehicle No :SMP4249K

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC FRT FENDER RH <i>Pistola d</i>	746.00 ✓	
2	1 PC FRT FENDER COWLING RH <i>Delet</i>	216.00 ✓	
3	1 PC FRT FENDER RETAINER RH <i>re</i>	56.00 ✓	
4	1 PC FRT BUMPER <i>Delet</i>	1,551.00 ✓ <i>1392</i>	
5	1 PC FRT BUMPER PARKING SENSOR <i>re</i>	287.00 +	
6	1 PC FRT BUMPER INNER SIDE RETAINER RH <i>re</i>	190.00 ✓	
7	1 PC FRT BUMPER WIPER SPRAY COVER RH <i>re</i>	78.00 +	
8	1 PC HEADLAMP RH <i>and d</i>	2,873.00 ✓ <i>1466</i>	
9	1 PC FRT SPORTS RIM RH <i>cut</i>	1,383.00 ✓ <i>1000 (SV)</i>	
		7,380.00	
	Less 10%	738.00	6,642.00
Special Net			
10	1 SET FRT FENDER COWLING CLIPS RH <i>re</i>	60.00 <i>80</i>	
11	1 SET FRT BUMPER CLIPS	60.00 <i>40</i>	
		120.00	120.00
Labour			
12	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS AND CUTTING/WELDING WORKS.	750.00 <i>500</i>	
13	1 TO SPRAY PAINTING	700.00 <i>500</i>	
14	1 TO SPRAY UNDERSEAL	80.00 +	
15	1 TO CHECK WIRING	50.00 <i>30</i>	
16	1 TO REMOVE AND REPLACE PARKING SENSOR	100.00 <i>50</i>	
		1,680.00	1,680.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2000193

Date: 16 Sep 2020

Veh Reg No: SMP4249K

Make/Model: M.BENZ CLA180 (R18 BI SR)

Chasis No: WDD1173422N190142

Reg. Date: 18/06/2015

Your Ref No: ES9120T

Claim Type: Third Party

Accident Date: 15/09/2020

TP Veh Reg No: ES9120T

Estimate Repair Cost to Vehicle No :SMP4249K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 8,442.00
	Add GST @ 7%		590.94
	Total Amount Payable		<u>S\$ 9,032.94</u>

TOTAL: SINGAPORE DOLLAR NINE THOUSAND THIRTY TWO AND CENTS NINETY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Adrian L
1/5 18/09/20

05 Days
total: 723420

1/5: 58K

5.8K

05 Days