

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 21 Sep 2020

**Preliminary Advice**

Insured Vehicle No	: SLZ5744A	Accident Date	: 30/08/2020
TP Vehicle No	: FBA2892A	Assignment Date	: 18/09/2020
Make	: KTM 950 ADVENTURE	Est. Duration of Repair	: 4
Date of Inspection	: 21/09/2020		
Inspection At	: DIRT WHEEL MOTOR TRADING (HQ) BLK 9004 TAMPINES STREET 93, #01-100 SINGAPORE 528838		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,155.50
Revised Amount	:S\$	8,237.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,237.50

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :