

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 01 Oct 2020

Preliminary Advice

Insured Vehicle No : YQ1638T
TP Vehicle No : SH9667A
Make : HYUNDAI AE IONIQ HEV DCT
Date of Inspection : 21/09/2020
Inspection At : BIFROST AUTO PTE LTD (SIN MING) (HQ)
BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE
SINGAPORE 575644
Accident Date : 18/09/2020
Assignment Date : 21/09/2020
Est. Duration of Repair : 6

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,174.64
Revised Amount	:S\$	3,360.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,360.76

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
() The vehicle is not economical for repair
() Part-by-Part repair
() Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.