



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

to Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Lim Boon Wee Reg No/Reg Date SJB9910K / 18/04/201 Date In/Mileage / 73364 Chassis No KNACC81CVH5062283 Engine No G4LEHS186125 Make/Model KIA/NIRO 1.6 A Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	21/09/2020/ 11:13	QUD	247 / DonBong	21361

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, CUT/WELD REAR END PANEL, REPAIR REAR TAILGATE ASSY 4 th				400 2000.00 1200
E PNT88000 REMOVE AND INSTALL REAR PARKING SENSOR				60.00
E PNT88000 REMOVE AND INSTALL REAR BOOT CABIN COMPARTMENT TO FACILITATE REPAIR WORK				120 150.00
E PNT98000 PAINT WORK SPRAY REAR END PANEL, REAR TAILGATE, 1 REAR BUMPER, RH REAR FENDER, LH REAR FENDER AND AFFECTED PORTION				1050 2100.00
E PNT88000 RENEW ACCIDENT ON FRONT BUMPER ABSORBER, LOWER COVER BUMPER, REPAIR FRONT BUMPER FACE				400 800.00
E PNT98000 PAINT WORK SPRAY FRONT BUMPER FACE AND AFFECTED PORTION				350 700.00
A 50000001 REMOVE AND REPLACE REAR EXHASUT				200 400.00
M SUNDRY APPLY BODY SEALANT				40 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00
M SUNDRY PERFORM RUST PREVENTION				40 80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUPPLY C&C LOGO				40.00
M SUNDRY RE-APPLY ZERTONA ON AFFECTED PORTION 8 x 3				240 400.00
A 54900099 TO DISMANTLE REAR HYBRID BATTERY PACK TO FACILITATE				X ? 400.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Lim Boon Wee Reg No/Reg Date SJB9910K / 18/04/201 Date In/Mileage / 73364 Chassis No KNACC81CVH5062283 Engine No G4LEHS186125 Make/Model KIA/NIRO 1.6 A Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	21/09/2020/ 11:13	QUD	247 / DonBong	21361
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
REPAIR WORK					
M SUNDRY					
SUPPLY FRONT AND REAR NUMBER PLATE WITH FRAME				✓ 100.00	
M SUNDRY				27 50.00	
SUNDRIES					
M EMBLEM-NIRO / MC	1.00	25.00	20.00	20.00	
M LOGO-KIA / MC	1.00	42.00	20.00	33.60	
M EMBLEM-ECO HYBRID / MC	1.00	29.00	20.00	23.20	
M PANEL ASSY-BACK	1.00	526.00	20.00	420.80	
M BRACKET ASSY-RR BUMPER SIDE, LH / MC	1.00	25.00	20.00	20.00	
M BRACKET ASSY-RR BUMPER SIDE, RH / MC	1.00	25.00	20.00	20.00	
M STAY-RR BUMPER LH	1.00	67.00	20.00	53.60	
M STAY-RR BUMPER RH	1.00	67.00	20.00	53.60	
M BRACKET-RR BEAM UPR MTG, LH	1.00	6.00	20.00	4.80	
M BRACKET-RR BEAM UPR MTG, RH	1.00	6.00	20.00	4.80	
M ANTENNA ASSY-SMARTKEY	1.00	39.00	20.00	31.20	
M BEAM-RR BUMPER	1.00	261.00	20.00	208.80	
M BRACKET-RR RAIL LWR MTG	1.00	6.00	20.00	4.80	
M BRACKET-RR BEAM LWR, CTR	1.00	6.00	20.00	4.80	
M BRACKET-SMART KEY MTG	1.00	5.00	20.00	4.00	
M WIRING HARNESS-RR BUMPER	1.00	361.00	20.00	288.80	
M REFLECTOR/REFLEX ASSY-RR LH	1.00	104.00	20.00	83.20	
M REFLECTOR/REFLEX ASSY-RR RH	1.00	104.00	20.00	83.20	
M GROMMET ASSY-SCREW	2.00	2.00	20.00	3.20	
M COVER-RR BUMPER, UPR	1.00	486.00	20.00	388.80	
M COVER-RR BUMPER LWR	1.00	392.00	20.00	313.60	
M SKID PLATE-RR BUMPER	1.00	122.00	20.00	97.60	
M PIECE-RR BUMPER SIDE, LH	1.00	16.00	20.00	12.80	
M PIECE-RR BUMPER SIDE, RH	1.00	16.00	20.00	12.80	
M COVER-RR BUMPER SIDE UNDER, LH	1.00	27.00	20.00	21.60	
M CLIP	10.00	1.00	20.00	8.00	
M COVER-RR BUMPER SIDE UNDER, RH	1.00	27.00	20.00	21.60	
M MOULDING ASSY-RR BUMPER SIDE, L	1.00	20.00	20.00	16.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



eg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Lim Boon Wee Reg No/Reg Date SJR9910K / 18/04/201 Date In/Mileage / 73364 Chassis No KNACCB1CVH5062283 Engine No G4LEHS186125 Make/Model KIA/NIRO 1.6 A Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	21/09/2020/ 11:13	QUD	247 / DonBong	21361	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	MOULDING ASSY-RR BUMPER SIDE,R	BR	1.00	20.00	20.00	16.00
M	SENSOR ASSY-PARKING ASSIST SYS	BR	1.00	135.00	20.00	108.00
M	SENSOR ASSY-PARKING ASSIST SYS	BR	1.00	135.00	20.00	108.00
M	SENSOR ASSY-PARKING ASSIST SYS	X N/A	1.00	135.00	20.00	108.00
M	SENSOR ASSY-PARKING ASSIST SYS	X N/A	1.00	135.00	20.00	108.00
M	LAMP ASSY-LICENSE PLATE,RH	BR	1.00	27.00	20.00	21.60
M	LAMP ASSY-LICENSE PLATE,LH	BR	1.00	27.00	20.00	21.60
M	PANEL-HEAT PROTECTOR,RR	BT	1.00	60.00	20.00	48.00
M	MUFFLER ASSY-REAR	BT	1.00	840.00	20.00	672.00
M	MUFFLER ASSY-CENTER	BT	1.00	658.00	20.00	526.40
M	LOGO ASSY-KIA SUB	N/A	1.00	51.00	20.00	40.80
M	GRILLE-FRONT BUMPER	X N/A	1.00	232.00	20.00	185.60
M	ABSORBER-FRONT BUMPER ENERGY	X N/A	1.00	68.00	20.00	54.40
M	COVER ASSY-FR BUMPER LWR	X R	1.00	346.00	20.00	276.80

SURVEYOR NAME: Steve CLKK) 8322 8813

SURVEYOR SIGNATURE: _____

DATE: 21/9/20, 1:39 pm

REMARKS: P/P, Ry Rel spy
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

- Confirm & accepted by
- Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorised signatory and company stamp

Nett 12,064.40
 7% GST on 12064.40 844.51
Total Payable 12,908.91

Validity of this estimate is 10 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.