

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

LKK Survey
22/9 = AMAM

19, SEP 2020

AIG Asia Pacific Insurance PL
78 Shenton Way
AIG Building
#07-16 S 079120

Not Authorized
11 Rm @ 900p
Resurvey Bk After Paint
2 days

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SMH292C
Accident involving vehicle no: SKA783M/SMH292C
DOA: 16092020 AT Pasir Ris Dr 8 twds Pasir Ris DR 1

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SKA783M

To supply--

Description	Qty	Amount
Rear bumper <i>broken</i>	1	815.00 ✓
Rear bumper reflector	1 <i>PL</i>	20.00 X
Rear bumper lower bracket @20	2 <i>PL</i>	40.00 X
Parts <i>10%</i>		875.00
Parts less 20%		175.00
		700.00

Reverse sensor
To remove damaged parts and attachments
Repair/reshape end panel, damaged areas
Replace/align rear bumper into position
To spray paint

SM 220.00 X

700.00 *2000*

500.00 *2000*

2,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: