

Not Assailed
11 Sep @ 1200

AAD2009-093

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5389K

Vehicle No.:
Chassis No.:
Vehicle Make: **18 SEP 2020**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC 5389K
VF1ABL15AUC280057
RENAULT
LATITUDE
16.9.2020
CHINA TAIPING
21/10/2014

PART

1 DOOR MIRROR ASSY LH

	LIST
\$	<i>CM</i> 1,483.40 ✓
TOTAL	\$ 1,483.40
10%	\$ 148.34
	\$ 1,335.06

Special Nett

1 Front Door Sticker "Trans-Cab"
1 Front Door Sticker "Classic"

\$	<i>nn</i> 80.00 X
\$	<i>nn</i> 80.00 X
TOTAL	\$ 160.00

TOTAL PARTS \$ 1,495.06

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 1,000.00 *601*

Putty and spray painting of the affected portion.

\$ 1,000.00 *601*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

TOTAL \$ 2,170.00

Over All Total \$ 3,665.06

LUMP SUM (REPAIR DAY)

18 days

1 day

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: