

CARZ HAVEN PTE. LTD.
60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869
Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO: LKK - SUN PIN
Surveyor Name and Company

Date of Accident : 20/9/2020

BILL TO: MSIG
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SKZ9330X

COST OF CLAIMS

Parts Cost / List : \$ 3,324.10

Supp. Parts : \$ -

Special Nett : \$ 35.00

Total Parts : \$ 2,528.08

Total Labour : \$ 1,190.00

TOTAL REPAIR COST : \$ 3,718.08

Total Parts Cost/List :	\$ 3,324.10
Plus / Less : 25%	\$ 831.03
Total :	\$ 2,493.08

Lump Sum Discount : 20%	\$ 743.62
Lump Sum Amount:	\$ 2,974.46

Final Lump Sum Amount : \$ 2,950.00

Submitted by / Date : PAULO

No. of Repair Days: 3

Confirmed by / Date : _____

CARZ HAVEN PTE.LTD.

60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKZ9330X**
 Vehicle Reg. Date: **16/2/2016**
 Make / Model : **TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT**
 Engine No. : **1ZRX534006**
 Chassis No. : **MR053REH104539903**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BONNET	X R	\$ 1,248.50		
2	2	BONNET HINGE LH/RH	X Svc	\$ 117.80		
3	1	BONNET LOCK	X Svc	\$ 135.00		
4	1	BONNET INSULATOR	X Svc	\$ 280.10		
5	1set	BONNET INSULATOR CLIPS	X Svc	\$ 20.00		
6	1	FRONT BUMPER	/CR4	\$ 531.10		\$ 531.10
7	1set	FRONT BUMPER CLIPS	/Nec	\$ 30.00		\$ 30.00
8	1	FRONT BUMPER RETAINER LH/RH	/Mis	\$ 171.00		\$ 85.50
9	1	FRONT BUMPER SPONGE	/CR4	\$ 90.10		\$ 90.10
10	1	FRONT BUMPER REINFORCEMENT	X Svc	\$ 399.50		
11	1	FRONT BRACE BRACKET	X Svc	\$ 149.90		
12	1	FRONT GRILLE LOGO	/Nec	\$ 47.90		\$ 47.90
13	1	FRONT UPPER GRILLE BASE	/CRA	\$ 643.00		\$ 643.00
14	1	FRONT UPPER GRILLE CHROME	X Svc			
15	1	FRONT LOWER GRILLE	/C4H	\$ 170.10		\$ 170.10
16	1	FOG LAMP RH	X Svc	\$ 310.40		
17	1	FOG LAMP GARNISH RH	X Svc	\$ 121.00		
18	1	HEAD LAMP RH	/SCR	\$ 724.40		\$ 724.40
19	1	HEAD LAMP CHROME GARNISH RH	X Svc	\$ 157.00		
20	1	HEAD LAMP SUPPORT RH	X R	\$ 167.00		
21	1	FRONT TOP SUPPORT PANEL	X R	\$ 1,136.30		
22	1	FRONT FENDER RH	X R	\$ 908.70		
23	1	FRONT FENDER EMBLEM RH	/Nec	\$ 35.50		\$ 35.50
24	1	FRONT FENDER INNER SHIELD RH	/C4H	\$ 209.10		\$ 209.10
25	1set	FRONT FENDER INNER SHIELD RH CLIPS	/Nec	\$ 20.00		\$ 20.00
26	1	FRONT ENGINE UNDERCOVER	/C4H	\$ 217.00		\$ 217.00
27	1set	FRONT ENGINE UNDERCOVER CLIPS	/Nec	\$ 30.00		\$ 30.00
28	1	FRONT RIM RH	/C4H	\$ 490.40		\$ 490.40
29	1	FRONT SHOCK ABSORBER RH	X Svc	\$ 438.30		
30	1	FRONT SHOCK MOUNTING RH	X Svc	\$ 219.10		
31	1	FRONT LOWER ARM RH	X Svc	\$ 732.50		
32	1	FRONT BALL JOINT RH	X Svc	\$ 263.30		
33	1	FRONT KNUCKLE ARM RH	X Svc	\$ 628.40		
34	1	FRONT WHEEL HUB RH	X Svc	\$ 261.30		
35	1	FRONT WHEEL BEARING RH	X Svc	\$ 120.60		
36	1	FRONT STABILIZER LINK RH	X Svc	\$ 237.10		
37	1	WASHER TANK	X Svc	\$ 219.10		
38	1	WASHER TANK MOTOR	X Svc	\$ 293.00		
39	1	FRONT TYRE RH	X Svc			
40	1	FRONT NUMBER PLATE WITH FRAME	/CR4		\$ 35.00	
				\$ 35.00	\$ 3,324.10	

3,326.10
 - 25%
 2,494.58

S/N = 35

60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869
Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

Estimates on Labour

[illegible]

\$ 1,190.00

$$\begin{array}{r} 2,494.58 \\ 35 \\ \hline 1,190 \\ 3,719.58 \\ - 20\% \\ \hline 2,975.66 \end{array}$$

4/5
\$ 2,950
3 days

CARZ HAVEN PTE.LTD.

60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKZ9330X**
 Vehicle Reg. Date: **16/2/2016**
 Make / Model : **TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT**
 Engine No. : **1ZRX534006**
 Chassis No. : **MR053REH104539903**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BONNET	X R			
2	2	BONNET HINGE LH/RH	X			
3	1	BONNET LOCK	X			
4	1	BONNET INSULATOR	X			
5	1set	BONNET INSULATOR CLIPS	X			
6	1	FRONT BUMPER	/ CRU			
7	1set	FRONT BUMPER CLIPS	/ NEC			
8	1	FRONT BUMPER RETAINER LH/RH	/ MIS.			
9	1	FRONT BUMPER SPONGE	/ CRU			
10	1	FRONT BUMPER REINFORCEMENT	X			
11	1	FRONT BRACE BRACKET	X			
12	1	FRONT GRILLE LOGO	/ NEC			
13	1	FRONT UPPER GRILLE BASE	/ CRA			
14	1	FRONT UPPER GRILLE CHROME	X			
15	1	FRONT LOWER GRILLE	/ CUT.			
16	1	FOG LAMP RH	X			
17	1	FOG LAMP GARNISH RH	X			
18	1	HEAD LAMP RH	/ SCR			
19	1	HEAD LAMP CHROME GARNISH RH	X			
20	1	HEAD LAMP SUPPORT RH	X R			
21	1	FRONT TOP SUPPORT PANEL	X R			
22	1	FRONT FENDER RH	X R			
23	1	FRONT FENDER EMBLEM RH	/ NEC.			
24	1	FRONT FENDER INNER SHIELD RH	/ CUT.			
25	1set	FRONT FENDER INNER SHIELD RH CLIPS	/ NEC			
26	1	FRONT ENGINE UNDERCOVER	/ CUT.			
27	1set	FRONT ENGINE UNDERCOVER CLIPS	/ NEC.			
28	1	FRONT RIM RH	/ CUT.			
29	1	FRONT SHOCK ABSORBER RH	X			
30	1	FRONT SHOCK MOUNTING RH	X			
31	1	FRONT LOWER ARM RH	X			
32	1	FRONT BALL JOINT RH	X			
33	1	FRONT KNUCKLE ARM RH	X			
34	1	FRONT WHEEL HUB RH	X			
35	1	FRONT WHEEL BEARING RH	X			
36	1	FRONT STABILIZER LINK RH	X			
37	1	WASHER TANK	X			
38	1	WASHER TANK MOTOR	X			
39	1	FRONT TYRE RH	X		\$ 300.00	
40	1	FRONT NUMBER PLATE WITH FRAME	/ CRU.		\$ 50.00	35

60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869
Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

[illegible]

Repair dy - 3 dgs

215

After pain photo

Sun Pm (4/11)

~~22~~ 22/09/2020

Tip without prejudice

Customer:		Date:	23-Sep-20 2:14 PM
Company:		VIN	
License No:	SKZ9330X	Technician:	IVAN
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

TOYOTA (MY), ALTIS, 2008-2008, ZZE 14

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2.1°	3.6°	----
		Right	----	2.1°	3.6°	----
	Camber	Left	-1.3°	-1.3°	0.2°	-1.4°
		Right	-1.2°	-1.3°	0.2°	-3.8°
	Toe	Left	-0.05°	-0.10°	0.10°	-0.10°
		Right	0.15°	-0.10°	0.10°	-4.00°
Total		0.10°	-0.20°	0.20°	-4.10°	
Rear	Camber	Left	-1.8°	----	----	-1.7°
		Right	-1.3°	----	----	-1.3°
	Toe	Left	0.05°	----	----	-0.10°
		Right	0.15°	----	----	0.35°
		Total	0.20°	----	----	0.25°
Thrust Angle		0.1°	----	----	0.2°	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	11.8°	13.3°	----
	Right		----	11.8°	13.3°	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-5mm	----	----	-2mm
	Rear		-4mm	----	----	-9mm
Track Width Diff.			0mm			16mm
Wheel Base Diff.			-1mm			7mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----

G

Customer:		Date:	23-Sep-20 2:14 PM
Company:		VIN	
License No:	SKZ9330X	Technician:	IVAN
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

TOYOTA (MY), ALTIS, 2008-2008, ZZE 14

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2.1°	3.6°	----
		Right	----	2.1°	3.6°	----
	Camber	Left	-1.3°	-1.3°	0.2°	-1.3°
		Right	-1.2°	-1.3°	0.2°	-1.2°
	Toe	Left	-0.05°	-0.10°	0.10°	-0.10°
		Right	0.15°	-0.10°	0.10°	-0.05°
Total		0.10°	-0.20°	0.20°	-0.15°	
Rear	Camber	Left	-1.8°	----	----	-1.7°
		Right	-1.3°	----	----	-1.3°
	Toe	Left	0.05°	----	----	0.05°
		Right	0.15°	----	----	0.20°
		Total	0.20°	----	----	0.25°
	Thrust Angle		0.1°	----	----	0.1°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	11.8°	13.3°	----
	Right		----	11.8°	13.3°	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-5mm	----	----	-5mm
	Rear		-4mm	----	----	-5mm
Track Width Diff.			0mm			2mm
Wheel Base Diff.			-1mm			0mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----

④