



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2106060

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 27/08/2021
Reference CC4/FCI20010101/Aea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 2099D
Insured Veh. SHA 9730S
Claim No. D20003794MFSH
Policy No. D-20094921MFSH
Accident Date 17/09/2020
Inspection Date 22/09/2020

Description	Total
Survey Inspection	165.00
Digital Photographs	
Transportation	
Subtotal	165.00
GST (7%)	11.55
Grand Total	176.55

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010101/Aea3q2	
			Date: 27/08/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9730S	Veh. Inspected	SLF 2099D	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20003794MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	21/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850HX200554	Colour	GREY	
Odometer	59130 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/09/2020	Inspection Date	22/09/2020	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 2099D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	671.50	523.00
5	FRT BUMPER CLIPS @\$4.20	NECESSARY	21.00	21.00
1	FRT BUMPER SIDE HOLDER LH	NECESSARY	23.10	23.10
1	FRT FENDER INNER LINER LH	DEFORMED	87.50	87.50
5	FRT FENDER INNER LINER CLIPS	NECESSARY	21.00	21.00
1	FRT FOGLAMP GARNISH LH	NOT NECESSARY	54.90	-
	LESS 20% DISCOUNT		-175.80	-135.12
			703.20	540.48
	<u>LABOUR</u>			
	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT .		300.00	250.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		500.00	400.00
			800.00	650.00
	GRAND TOTAL		1,503.20	1,190.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00

Report Ref No. CC4/FCI20010101/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 2099D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

