

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0681/2020/NS
DATE : 21-Sep-20
WIP : 50035

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

*Hi Adrian,
6 days - ok - Jy - 18 Dec 20*

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAN QINGCHENG RYAN
ADDRESS : 21 DELTA ROAD
#18-02
SINGAPORE 169813
TELEPHONE : HP +65 96808787
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900166839
VEHICLE NO : SMQ 885 U
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 25/09/2019
ENGINE NO : CVK 086892
CHASSIS NO : WAUZZZF47KA110579
MILEAGE : 6123KM
DATE IN : 18-Sep-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Sep-20
PLACE OF ACCIDENT : 10.2KM INTO CTE



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 885 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 350.00	\$	250.00
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N	\$ 350.00		
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 2,800.00	\$	1,500.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, BONNET HINGES AND RHS FRONT DOOR.		\$ 3,000.00	\$	1,810.00
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT TEST.	S/N	\$ 520.00	\$	280.00
7	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$ 7,884.00	\$	4,704.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER		\$	2,171.00	\$ 1,736.80
2	FRONT BUMPER FIXING PARTS		\$	580.00	
3	FRONT BUMPER SECURING STRIP	2	\$	70.00	\$ 55.68
4	FRONT BUMPER GRILLE - CENTRE		\$	194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$	208.00	
6	FRONT BUMPER AIR GUIDE - RH		\$	62.00	\$ 49.52
7	RADIATOR GRILLE		\$	2,160.00	\$ 1,728.00
8	FRONT BUMPER AIR GUIDE GRILLE - RH		\$	361.00	\$ 288.80
9	FRONT BUMPER CARRIER		\$	795.00	
10	FRONT BUMPER FOAM FILLER PIECE		\$	123.00	
11	FRONT BUMPER GUIDE SECTION - RH		\$	37.00	\$ 29.52
12	FRONT BUMPER TOP COVER		\$	126.00	\$ 100.40
13	CAUTION SIGN STICKER	NEC	\$	14.00	\$ 10.80
14	AIRCON STICKER	NEC	\$	8.00	\$ 5.68
15	LOCK CARRIER BRACKET		\$	136.00	\$ 108.40
16	FRONT BUMPER SUPPORT - LH / RH	2	\$	56.00	\$ 22.24
17	FRONT PARKING AID SENSOR - INNER / OUTER	2		TBC	\$ 386.08
18	FRONT FENDER - RH		\$	758.00	\$ 606.00
19	FRONT FENDER ATTACHMENT PARTS		\$	200.00	
20	FRONT FENDER CLOSING ELEMENT - RH		\$	49.00	\$ 39.20
SUB TOTAL SPARE PARTS		:	\$	8,108.00	\$ 5,167.12

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
		<i>c/f</i>		\$	5,167.12
21	FRONT FENDER BRACKET - RH		\$	35.00	\$ 27.60
22	DEFORMATION ELEMENT BRACKET - RH		\$	49.00	\$ 38.80
23	FRONT FENDER BRAK CET		\$	31.00	\$ 24.80
24	FRONT FENDER BRACKET		\$	33.00	\$ 26.32
25	FRONT FENDER BRACE - RH		\$	117.00	\$ 93.60
26	FRONT FENDER CLOSING ELEMENT - RH		\$	33.00	
27	FRONT FENDER COVER - RH		\$	12.00	\$ 9.04
28	WHEEL HOUSING LINER - RH		\$	239.00	\$ 190.80
29	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	230.00	
30	WHEEL SPOILER - RH		\$	73.00	
31	WHEEL SPOILER TRIM - RH		\$	36.00	
32	STONE CHIP GUARD - RH		\$	50.00	\$ 39.92
33	BONNET		\$	2,763.00	\$ 2,210.40
34	BONNET ATTACHMENT PARTS		\$	408.00	
35	BONNET LID HINGE - LH / RH	2	\$	602.00	\$ 481.60
36	BONNET IMPACT PROTECTION - CENTRE		\$	27.00	\$ 21.52
37	BONNET IMPACT PROTECTION - LH		\$	28.00	\$ 21.84
38	BONNET IMPACT PROTECTION - RH		\$	27.00	\$ 21.52
39	TOP FENDER INNER COVER - RH		\$	61.00	\$ 48.24
40	TOP FENDER LEDGE COVER - UPPER RH		\$	31.00	\$ 24.40
SUB TOTAL SPARE PARTS		:	\$	4,885.00	\$ 8,447.52

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
		<i>c/f</i>		\$	8,447.52
41	TOP FENDER LEDGE COVER - LOWER RH		\$	23.00	\$ 17.68
42	BONNET GAS FILLED STRUT		\$	118.00	\$ 94.00
43	BONNET STRIKER - LH / RH	2	\$	100.00	\$ 78.88
44	BONNET LID LOCK		\$	212.00	
45	PLENUM CHAMBER COVER		\$	96.00	\$ 76.64
46	BONNET SOUND ABSORBER		\$	339.00	
47	LED HEADLIGHT - RH		\$	7,693.00	\$ 6,154.40
48	MAIN LIGHT ELECTRONICS POWR MODULE		\$	739.00	
49	LIGHT CONTROL SYSTEM CONTROL UNIT		\$	742.00	
50	HEADLAMP REPAIR KIT - RH		\$	130.00	
51	HEADLIGHT HOSE - RH		\$	36.00	
52	HEADLIGHT COMPENSATING PIECE		\$	40.00	
53	HEADLIGHT COMPENSATING PIECE		\$	40.00	
54	HEADLIGHT COMPENSATING PIECE		\$	40.00	
55	LIFT CYLINDER - RH		\$	208.00	
56	LIFT CYLINDER CORRUGATED PIPE		\$	92.00	
57	LIFT CYLINDER CORRUGATED PIPE		\$	38.00	
58	HEADLIGHT WASHER PUMP		\$	151.00	
59	WASH WATER RESERVOIR		\$	146.00	\$ 116.40
60	WINDSCREEN WASHER SYSTEM PUMP		\$	121.00	
SUB TOTAL SPARE PARTS		:	\$	11,104.00	\$ 14,985.52

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
	<i>c/f</i>		\$	14,985.52
61 WINDOW SLOT SEAL - RH		\$	303.00	
62 WINDOW GUIDE TRIM STRIP		\$	254.00	
63 FRONT ALUMINIUM RIM - RH			TBC \$	80.00
64 FRONT TYRE - RH		\$	410.00	\$ 410.00
65 SUPPLEMENTARY		\$	565.00	\$ 463.60
66 SUNDRIES		\$	350.00	\$ 31.52
TOTAL SPARE PARTS	:	\$	25,979.00	\$ 15,970.64
TOTAL LABOUR CHARGES	:	\$	7,884.00	\$ 4,704.00
GRAND TOTAL	:	\$	33,863.00	\$ 20,674.64

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0681/2020/NS
Date 23-Sep-20
Service Advisor Glory Tan
Pages 1 OF 1
Regn No SMQ 885 U
Model No AUDI A4 SEDAN 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
Parts			
1	Front number plate	\$ 60.00	\$ 60.00
2	Front bumper wiring set	\$ 505.00	\$ 403.60
TOTAL		\$ 565.00	\$ 463.60

For Premium Automobiles Pte Ltd

Authorised Signature