

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0681/2020/NS
DATE	:	21-Sep-20
WIP	:	50035

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR TAN QINGCHENG RYAN
ADDRESS	:	21 DELTA ROAD
		#18-02
		SINGAPORE 169813
TELEPHONE	:	HP +65 96808787
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900166839
VEHICLE NO	:	SMQ 885 U
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR	:	25/9/2019
ENGINE NO	:	CVK 086892
CHASSIS NO	:	WAUZZZF47KA110579
MILEAGE	:	6123KM
DATE IN	:	18-Sep-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	18-Sep-20
PLACE OF ACCIDENT	:	10.2KM INTO CTE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMO 885 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 350.00 X.	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 1500.	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, BONNET HINGES AND RHS FRONT DOOR.	\$ 3,000.00 1810	$3 \times 550 = 1650$ Hinge $\times 2 = 80 \times 2 = 160$
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT TEST.	S/N \$ 520.00 260 - 280	
7	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,884.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Distorted</i>		\$	2,171.00 ✓	1736.80
2 FRONT BUMPER FIXING PARTS <i>Not new</i>		\$	580.00 ? X	
3 FRONT BUMPER SECURING STRIP <i>Engl</i>	2	\$	70.00 ✓	55.68
4 FRONT BUMPER GRILLE - CENTRE <i>Not new</i>		\$	194.00 *	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not new</i>		\$	208.00 ? X	
6 FRONT BUMPER AIR GUIDE - RH <i>Missing</i>		\$	62.00 ✓	49.52
7 RADIATOR GRILLE <i>Excluded.</i>		\$	2,160.00 ? ✓	1728.00
8 FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>		\$	361.00 ✓	288.80
9 FRONT BUMPER CARRIER <i>new</i>		\$	795.00 +	
10 FRONT BUMPER FOAM FILLER PIECE <i>new</i>		\$	123.00 ✓	
11 FRONT BUMPER GUIDE SECTION - RH <i>Damaged</i>		\$	37.00 ✓	29.52
12 FRONT BUMPER TOP COVER <i>Cracked</i>		\$	126.00 ✓	100.40
13 CAUTION SIGN STICKER <i>?</i>	NEC	\$	14.00 ✓	10.80
14 AIRCON STICKER <i>new</i>	NEC	\$	8.00 ✓	5.68
15 LOCK CARRIER BRACKET <i>Excluded.</i>		\$	136.00 ? ✓	108.40
16 FRONT BUMPER SUPPORT - LH / RH <i>RH and LH d.</i>	2	\$	56.00 28 ✓	22.24
17 FRONT PARKING AID SENSOR - INNER / OUTER <i>outer missing</i>	2	\$	193.04 TBC ✓	386.08
18 FRONT FENDER - RH <i>Distorted.</i>		\$	758.00 ✓	606.00
19 FRONT FENDER ATTACHMENT PARTS <i>Not new</i>		\$	200.00 ? X	
20 FRONT FENDER CLOSING ELEMENT - RH <i>Best</i>		\$	49.00 ✓	39.20
SUB TOTAL SPARE PARTS		:	\$ 8,108.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
S/NETT				
21 FRONT FENDER BRACKET - RH <i>Best</i>	\$	35.00 ✓	27.60	
22 DEFORMATION ELEMENT BRACKET - RH <i>2nd</i>	\$	49.00 ✓	38.80	
23 FRONT FENDER BRACKET <i>2 Best</i>	\$	31.00 ✓	24.80	
24 FRONT FENDER BRACKET	\$	33.00 ✓	26.32	
25 FRONT FENDER BRACE - RH <i>Best</i>	\$	117.00 ✓	93.60	
26 FRONT FENDER CLOSING ELEMENT - RH <i>Best 2nd</i>	\$	33.00 ✓	? X	
27 FRONT FENDER COVER - RH <i>2nd</i>	\$	12.00 ✓	9.04	
28 WHEEL HOUSING LINER - RH <i>2nd</i>	\$	239.00 ✓	190.80	
29 WHEEL HOUSING LINER ATTACHMENT PARTS <i>2nd</i>	\$	230.00 ?	X	
30 WHEEL SPOILER - RH <i>2nd</i>	\$	73.00 +		
31 WHEEL SPOILER TRIM - RH <i>2nd</i>	\$	36.00 +		
32 STONE CHIP GUARD - RH <i>2nd</i>	\$	50.00 ✓	39.92	
33 BONNET <i>2nd</i>	\$	2,763.00 ✓	2210.40	
34 BONNET ATTACHMENT PARTS <i>2nd</i>	\$	408.00 ?	X	
35 BONNET LID HINGE - LH / RH <i>Best</i>	2 \$	602.00 ✓	481.60	
36 BONNET IMPACT PROTECTION - CENTRE <i>2nd</i>	\$	27.00 ✓	21.52	
37 BONNET IMPACT PROTECTION - LH <i>2nd</i>	\$	28.00 ✓	21.84	
38 BONNET IMPACT PROTECTION - RH <i>2nd</i>	\$	27.00 ✓	21.52	
39 TOP FENDER INNER COVER - RH <i>2nd</i>	\$	61.00 ✓	48.24	
40 TOP FENDER LEDGE COVER - UPPER RH <i>2nd</i>	\$	31.00 ✓	24.40	
SUB TOTAL SPARE PARTS	:	\$	4,885.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	REMARKS
S/NETT			
41 TOP FENDER LEDGE COVER - LOWER RH <i>old.</i>	\$	23.00 ✓	17.68
42 BONNET GAS FILLED STRUT <i>new Deryd</i>	\$	118.00 ✓	94.00
43 BONNET STRIKER - LH / RH <i>2 But.</i>	2	\$ 100.00 + ✓	78.88
44 BONNET LID LOCK <i>free new</i>	\$	212.00 +	
45 PLENUM CHAMBER COVER <i>lt</i>	\$	96.00 ✓	76.64
46 BONNET SOUND ABSORBER <i>new</i>	\$	339.00 +	
47 LED HEADLIGHT - RH <i>canled</i>	\$	7,693.00 ✓	6154.40
48 MAIN LIGHT ELECTRONICS POWR MODULE <i>new</i>	\$	739.00 ? X	
49 LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	\$	742.00 ? X	
50 HEADLAMP REPAIR KIT - RH <i>new</i>	\$	130.00 ? X	
51 HEADLIGHT HOSE - RH <i>not new</i>	\$	36.00 X	
52 HEADLIGHT COMPENSATING PIECE <i>2</i>	\$	40.00 +	
53 HEADLIGHT COMPENSATING PIECE <i>free new</i>	\$	40.00 +	
54 HEADLIGHT COMPENSATING PIECE	\$	40.00 +	
55 LIFT CYLINDER - RH <i>new canled new</i>	\$	208.00 X	
56 LIFT CYLINDER CORRUGATED PIPE <i>new</i>	\$	92.00 +	
57 LIFT CYLINDER CORRUGATED PIPE <i>new</i>	\$	38.00 +	
58 HEADLIGHT WASHER PUMP <i>new</i>	\$	151.00 ? X	
59 WASH WATER RESERVOIR <i>canled</i>	\$	146.00 ? ✓	116.40
60 WINDSCREEN WASHER SYSTEM PUMP <i>new</i>	\$	121.00 ? X	
SUB TOTAL SPARE PARTS		\$ 11,104.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT	
61 WINDOW SLOT SEAL - RH	1	\$	303.00	✓
62 WINDOW GUIDE TRIM STRIP	1	\$	254.00	✓
63 FRONT ALUMINIUM RIM - RH	1		TBC	✓ 80.00
64 FRONT TYRE - RH	1	\$	410.00	✓
65 SUNDRIES	1	\$	350.00	✓ 31.52
TOTAL SPARE PARTS		:	\$ 25,414.00	
TOTAL LABOUR CHARGES		:	\$ 7,884.00	
GRAND TOTAL		:	\$ 33,298.00	34,329.08

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Lim
21/09/20

Not Authorised, 06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0681/2020/NS 23-Sep-20 Glory Tan 1 OF 1 SMQ 885 U AUDI A4 SEDAN 2.0 TFSI 8W
--	---	--

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front number plate <i>Mr</i>	\$ 60.00	✓
2	Front bumper wiring set <i>Snapped</i>	\$ 505.00	✓ 403.60
TOTAL		\$ 565.00	

For Premium Automobiles Pte Ltd

Adrian Ling
 24/09/20.
[Signature]

 Authorised Signature