

Car-in, WIP: 50035

Kiam / Keong



PREMIUM AUTOMOBILES

45 UBI ROAD 1 SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Distorted</i>	5	2,171.00 ✓	
2 FRONT BUMPER FIXING PARTS ?	5	580.00 ✓	
3 FRONT BUMPER SECURING STRIP <i>Distorted</i>	2	70.00 ✓	
4 FRONT BUMPER GRILLE - CENTRE <i>New</i>	5	194.00 ✓	
5 FRONT BUMPER CLOSING ELEMENT - LOWER ? CENTRE	5	208.00 ✓	
6 FRONT BUMPER AIR GUIDE - RH <i>Missing</i>	5	62.00 ✓	
7 RADIATOR GRILLE <i>Could</i>	5	2,160.00 ✓	
8 FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	5	361.00 ✓	
9 FRONT BUMPER CARRIER <i>New</i>	5	795.00 ✓	
10 FRONT BUMPER FOAM FILLER PIECE <i>New</i>	5	123.00 ✓	
11 FRONT BUMPER GUIDE SECTION - RH <i>Distorted</i>	5	37.00 ✓	
12 FRONT BUMPER TOP COVER <i>Could</i>	5	126.00 ✓	
13 CAUTION SIGN STICKER ?	NEC 5	14.00 ✓	
14 AIRCON STICKER <i>New</i>	NEC 5	8.00 ✓	
15 LOCK CARRIER BRACKET <i>Could</i>	5	136.00 ✓	
16 FRONT BUMPER SUPPORT - LH / RH <i>RH and outer missing</i>	2 5	56.00 ✓	28
17 FRONT PARKING AID SENSOR - INNER / OUTER	2 5	TBC ✓	24
18 FRONT FENDER - RH <i>Distorted</i>	5	758.00 ✓	
19 FRONT FENDER ATTACHMENT PARTS ?	5	200.00 ✓	
20 FRONT FENDER CLOSING ELEMENT - RH <i>Best</i>	5	49.00 ✓	
SUB TOTAL SPARE PARTS	:	\$ 8,108.00	

PREMIUM AUTOMOBILES



1001 ROAD 1, SINGAPORE 408699

TEL: 6345 2323 FAX: 6841 1183

EMAIL: SALES@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 FRONT FENDER BRACKET - RH <i>Best</i>	5	35.00 ✓	
22 DEFORMATION ELEMENT BRACKET - RH <i>Dmgd</i>	5	49.00 ✓	
23 FRONT FENDER BRACKET <i>? Best</i>	5	31.00 ✓	
24 FRONT FENDER BRACKET	5	33.00 ✓	
25 FRONT FENDER BRACE - RH <i>Best</i>	5	117.00 ✓	
26 FRONT FENDER CLOSING ELEMENT - RH <i>Best ?</i>	5	33.00 <i>Wrt ?</i>	
27 FRONT FENDER COVER - RH <i>Dmgd</i>	5	12.00 ✓	
28 WHEEL HOUSING LINER - RH <i>Dmgd</i>	5	239.00 ✓	
29 WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>	5	230.00 <i>?</i>	
30 WHEEL SPOILER - RH	5	73.00 <i>+</i>	
31 WHEEL SPOILER TRIM - RH <i>? New</i>	5	36.00 <i>+</i>	
32 STONE CHIP GUARD - RH <i>New</i>	5	50.00 ✓	
33 BONNET <i>Dented</i>	5	2,763.00 ✓	
34 BONNET ATTACHMENT PARTS	5	408.00 <i>?</i>	
35 BONNET LID HINGE - LH / RH <i>Best</i>	2	602.00 ✓	
36 BONNET IMPACT PROTECTION - CENTRE	5	27.00 ✓	
37 BONNET IMPACT PROTECTION - LH <i>? New</i>	5	28.00 ✓	
38 BONNET IMPACT PROTECTION - RH	5	27.00 ✓	
39 TOP FENDER INNER COVER - RH <i>Dmgd</i>	5	61.00 ✓	
40 TOP FENDER LEDGE COVER - UPPER RH <i>Dmgd</i>	5	31.00 ✓	
SUB TOTAL SPARE PARTS	:	\$ 4,885.00	

PREMIUM AUTOMOBILES



85 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S	S/NETT	
41 TOP FENDER LEDGE COVER - LOWER RH <i>old</i>		\$	23.00	✓
42 BONNET GAS FILLED STRUT <i>new</i>		\$	118.00	✓
43 BONNET STRIKER - LH / RH <i>new</i>	2	\$	100.00	✓
44 BONNET LID LOCK <i>new</i>		\$	212.00	✓
45 PLENUM CHAMBER COVER <i>new</i>		\$	95.00	✓
46 BONNET SOUND ABSORBER <i>new</i>		\$	339.00	✓
47 LED HEADLIGHT - RH <i>new</i>		\$	7,693.00	✓
48 MAIN LIGHT ELECTRONICS POWR MODULE ?		\$	139.00	?
49 LIGHT CONTROL SYSTEM CONTROL UNIT ?		\$	112.00	?
50 HEADLAMP REPAIR KIT - RH ?		\$	130.00	?
51 HEADLIGHT HOSE - RH <i>new</i>		\$	36.00	✓
52 HEADLIGHT COMPENSATING PIECE ?		\$	40.00	+
53 HEADLIGHT COMPENSATING PIECE <i>new</i>		\$	40.00	+
54 HEADLIGHT COMPENSATING PIECE <i>new</i>		\$	40.00	+
55 LIFT CYLINDER - RH <i>new</i>		\$	208.00	✓
56 LIFT CYLINDER CORRUGATED PIPE <i>new</i>		\$	92.00	+
57 LIFT CYLINDER CORRUGATED PIPE <i>new</i>		\$	38.00	+
58 HEADLIGHT WASHER PUMP ?		\$	151.00	?
59 WASH WATER RESERVOIR <i>new</i>		\$	146.00	✓
60 WINDSCREEN WASHER SYSTEM PUMP ?		\$	121.00	?
SUB TOTAL SPARE PARTS		\$	11,104.00	

Resurveyed 24/09/24
Adrian *[Signature]*

PREMIUM AUTOMOBILES



45 LEBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NOKA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 885 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
61 WINDOW SLOT SEAL - RH	1	\$ 303.00	✓
62 WINDOW GUIDE TRIM STRIP	1	\$ 254.00	✓
63 FRONT ALUMINIUM RIM - RH	1	TBC	✓
64 FRONT TYRE - RH	1	\$ 410.00	✓
65 SUNDRIES	1	\$ 350.00	?
TOTAL SPARE PARTS	:	\$ 25,414.00	
TOTAL LABOUR CHARGES	:	\$ 7,884.00	
GRAND TOTAL	:	\$ 33,298.00	

ALL CHARGES ARE INCLUSIVE OF GST
TEND.

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Supp
Front bumper with set.
Front No plate