

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Sep-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8938 L

1 pc	Boot lid	\$	1,119.00	bt
1 pc	Boot lid lock	\$	99.00	d's
1 pc	Bootlid lock cable	\$	35.00	X
1 pc	Bootlid striker	\$	21.00	Ry
1 pc	Bootlid emblem	\$	27.00	ne
1 pc	Bootlid CRDi	\$	29.00	ne
1 pc	Boot lid rubber weatherstrip	\$	96.00	th
1 pc	Boot lid lower garnish	\$	290.00	?
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	1?
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00	X
2 pcs	Bootlid hinge torsion bar @ \$33.00	\$	66.00	X
1 pc	Handle trunk lid hook	\$	5.00	X
1 pc	Bootlid inner trim	\$	190.00	X
1 pc	End panel - photo	\$	250.00	bt
1 pc	End panel inner garnish	\$	74.00	? photo
2 pcs	Rear n/s & o/s fenders \$1205.00	\$	2,410.00	X
2 pcs	Rear n/s & o/s fender inner shield @ \$120.00	\$	240.00	X
2 pcs	Rear n/s & o/s air vent @ \$30.00	\$	60.00	X
1 pc	Rear windscreen moulding	\$	87.00	X
1 pc	Rear bumper	\$	696.00	de
1 pc	Rear n/s & o/s fender top chrome moulding @ \$97.00	\$	194.00	X
1 pc	Rear bumper lower cover	\$	206.00	de
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	n/s? o/s de
1 pc	Rear bumper inner sponge	\$	114.00	de
1 pc	Rear bumper reinforcement	\$	607.00	? photo
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	?
2 pcs	n/s & o/s tail lamp @ \$421.00	\$	842.00	n/s? o/s de
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00	X
2 pcs	n/s & o/s tail lamp panel @ \$215.00	\$	430.00	Ry
1 pc	Spare tyre clamp	\$	6.00	X
1 pc	Exhaust pipe	\$	1,009.00	Ry
1 pc	Exhaust pipe hanger	\$	40.00	X

21-Sep-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8938 L

1 pc Floorboard panel
1 pc Floorboard panel trim

\$ 625.00 X
\$ 205.00 X
\$ 11,294.00
\$ 1,129.40
\$ 10,164.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/NETT

1 set Rear bumper clips
1 set End panel inner garnish clips
1 set Bootlid inner trim clips
1 set Bootlid lower garnish clips
1 set Bootlid stickers
2 set Rear n/s & o/s fender inner shield clips
1 set Reverse sensor
1 pc Rear bumper top protector
2 pcs Rear o/s & o/s fender stickers @ \$60.00
2 sets n/s & o/s door stickers @ \$100.00
1 set Floorboard compartment insulating paddings
1 pc Rear no. plate with casing
1 pc Sealant

\$ 48.00 300g ✓
\$ 30.00 100g ✓
\$ 52.00 X
\$ 60.00 200g ✓
\$ 100.00 200g ✓
\$ 56.00 X
\$ 280.00 200g ✓
\$ 80.00 X
\$ 120.00 X
\$ 200.00 X
\$ 120.00 X
\$ 50.00 X
\$ 50.00 300g ✓

Sundry

Towing Fee

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 50.00 200g ✓
\$ 50.00 ? towing receipt?
\$ 120.00 300g ✓

To dismantle / replace new exhaust pipe

\$ 120.00 60 plus?

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 60.

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s & o/s fenders. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s chassis

800
\$2,000.00

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s & o/s chassis member, rear n/s & o/s fenders, rear n/s & o/s tail lamp panels,

800
700
\$ 2,400.00

To apply rustproofing on the repaired and replaced panels.

\$ 500.00 50.
\$ 16,830.60