

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMS/616M
Rf.

at Workshop m/s

of

Insured:

FBP958913

Policy No.

Claims No.

CM102002753/AGC


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

155k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A 76776

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMS/616M

Yr Regn:

8/20

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

BMW X1 M-sport 1998

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

2206

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA72AA0405R 39536

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45 R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental/

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/9/20

D.O.I.

22/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

have video (glass coating w/tpaint correction package (\$898))

29/9/20 1/5 @ 2100 confirmed w/ Alan (Red # 5765, 73%)

29/9/20 @ 9.18am revised to Agnes Chan by email.

Date/Time, File Pass to?



Preli. Report

1) 30/9 typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format :

TP

Lump Sum / I.B.I. (\$

2100

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Not Authorized
2100 /
3 days.

VEHICLE No: SMS 1616M

1PC	FRONT DOOR O/S	
1PC	FRONT DOOR INNER RUBBER O/S	
1PC	REAR DOOR O/S	1203.60
1PC	REAR DOOR INNER RUBBER O/S	171.90
1PC	REAR DOOR FRAME STICKER O/S	185.00

(52)

R	\$2,480.00	X
11	\$315.00	X
Body	\$2,380.00	—
111	\$315.00	—
111	\$285.00	—
	\$5,775.00	

TO CHECK WIRING
TO RESET & REPROGRAMME SYSTEM
TO SPRAY RUST PROOFING
TO TRANSFER REAR DOOR MECHANISM
TO SPRAY CERAMIC COATING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

11	\$50.00	X
	\$150.00	80
	\$80.00	30
	\$100.00	60
	\$450.00	200
	\$580.00	380
	\$680.00	400
TOTAL	\$7,865.00	

2,1560.70
52
1482.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: