

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CS/CT120010120/4443

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJL 408B

at Workshop m/s

Riv - 60

of

Insured:

GSK5825

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$18

IDAC Accident Rpt:

Consistent? : Yes or No

GA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJL 408B

Yr Regn:

11, 08

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Lancer mives

1499

Colour

Red

A/C: Insured / Std / NI / NA

Sp.Reading

16/129

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSRCY2A 9U 000527

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Milder / Jammed / Leaked / Burnt or

Brake: Milder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45-22R18

BS / DUN / EXNOVA / GY / FS / EIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/9/20

D.O.I.

22/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

See 31-8-2023 Sol 2yrs 11mth.

MV \$18,000

LTA \$10,093

NV \$7907

6/10/20 4/5 \$6000 confirmed with EIF (Red 35,745.60, 86%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 6/10/20-Typist

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

: Photos

: Others

☐

: Interview (\$

☐

: Tech. Invs (\$


☐

: Weekend (\$

Report Format : Merimen

Lump Sum / B.L. (\$ 6,000/-

TOTAL



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJL 408 B
MITSUBISHI LANCER EX

mt Adnan
nil
1/5 56000/
22/9/20
the pte attn.

Submit to insurance

5 days.

ATTN	NO	DESCRIPTION - PARTS	QTY	PRICE	
	1	REAR WINDSCREEN MOULDING 111 X	1	\$377.00	X
	2	BOOT LID Body 20 885	1	\$1341.00	X
	3	BOOTLID THIRD BRAKE LAMP 11 X	1	\$352.00	X
	4	BOOT LID LOGO (MITSUBISHI) neu ✓ 42	1	\$105.00	✓
	5	BOOTLID EMBLEM (LANCER) neu ✓ 45	1	\$110.00	✓
	6	BOOTLID EMBLEM (EX) neu ✓ 38	1	\$95.00	✓
	7	BOOTLID EMBLEM (C&C) neu ✓ 45	1	\$107.00	✓
	8	BOOT LID LAMP (L+R) N/S CNE 12C 188 \$743.00	2	\$1486.00	1PC
	9	BOOT LID LOCK tw ✓ 109	1	\$359.00	✓
	10	BOOT LID LOCK CATCH 11 X	1	\$96.00	X
	11	BOOT LID INNER TRIM 22/7011 245.00	1	\$510.00	✓
	12	BOOT LID HINGE (L+R) 11 X	2	\$404.00	X
	13	BOOT LID DAMPER (L+R) 11 X	2	\$650.00	X
	14	BOOT LID STOPPER (L+R) 11 X	2	\$46.00	X
	15	BOOT LID WEATHER STRIP tw ✓ 185.00	1	\$375.00	✓
	16	TAIL LAMP (L+R) CNE 425 X 2 = 850	2	\$1794.00	✓
	17	TAIL LAMP PANEL (L+R) 2 X	2	\$850.00	X
	18	REAR BUMPER D.S ✓ 843.00	1	\$1268.00	✓
	19	REAR BUMPER RETAINER (L+R) N/S bent 12C 35.00 \$129.00	2	\$258.00	12C
	20	REAR BUMPR CENTER BRACKET NS X	1	nil	X
	21	REAR BUMPER REINFORCEMENT BAR 324 ✓ 245.00	1	\$789.00	✓
	22	REAR BUMPER BRACKET (L+R) NS X	2	\$490.00	X
	23	REAR BUMPER BEAM top 324 ✓ 105.00	1	\$743.00	✓
	24	REAR BUMPER SPONGE NS X	1	\$361.00	X
	25	REAR BUMPER REFLECTOR (L+R) CNE 32 X 2 = 64	2	\$282.00	✓
	26	REAR BUMPER CARPLATE LAMP (L+R) 11 X	2	\$256.00	X
	27	REAR BUMPER TOW COVER 712 ✓ 28.00	1	\$85.00	✓
	28	REAR FENDER (L+R) 12 X	2	\$5172.00	X
	29	REAR FENDER INNER TRIM (L+R) N/S 70.11 12C 265 \$811.00	2	\$1622.00	12C
	30	REAR FENDER COWLING (L+R) 11 X	2	\$490.00	X
	31	END PANEL 20 2500 442.00	1	\$1031.00	✓
	32	END PANEL TOP GARNISH tw ✓ 166.00	1	\$510.00	✓
	33	SPAREWHEEL PANEL 12 X	1	\$1376.00	X
	34	SPAREWHEEL PANEL TOP BOARD 11 X	1	\$682.00	X
	35	SPAREWHEEL PANEL TOP BOARD TOP MAT 11 X	1	nil	X
	36	EXHAUST PIPE 11 X	1	\$1090.00	X
	37	EXHAUST GASKET 11 X	1	\$251.00	X
	38	EXHAUST BRACKET (L+R) 11 X P: \$11,183	2	\$372.00	X
	39	EXHAUST HEAT SHIELD 11 X -10% = \$10,064.70	1	\$379.00	X

4825

26,584.00

SUBTOTAL

S

-

LESS 10%

S

-

23,925.80

PARTS TOTAL

S

-

SPECIAL NETT

QTY

PRICE

1	REAR WINDSCREEN SEALANT	11 X	1	\$	300.00	X
2	BOOTLID SPOILER	2x7 600	1	\$	3,000.00	600 X
3	BOOTLID INNER TRIM CLIPS	11 X	10	\$	100.00	X
4	TAIL LAMP CLIP (L+R)	11 X	4	\$	80.00	X
5	REAR BUMPER CLIPS	11 50	10	\$	100.00	50
6	REAR BUMPER REVERSE SENSOR (L+R)	Shipped 200	2	\$	300.00	200
7	REAR BUMPER REVERSE CAMERA	11 X	1	\$	850.00	X
8	REAR CARPLATE		1	\$	200.00	
9	REAR CARPLATE FRAME	1 BAO 40	1	\$	120.00	40
10	REAR FENDER SEALANT	11 X	2	\$	600.00	X
11	REAR FENDER INNER TRIM CLIPS	11 X	20	\$	200.00	X
12	REAR FENDER COWLING CLIPS	11 X	20	\$	200.00	X
13	END PANEL SEALANT	11 50	1	\$	250.00	50
14	SPAREWHEEL PANEL SEALANT	11 X	1	\$	350.00	X

S/N: \$940

940

SPECIAL NETT TOTAL

\$ 6,650.00

LABOUR

QTY

PRICE

1	TO R&R ACCIDENT AFFECTED AREA	850	1	\$	3,600.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREA	1100	1	\$	3,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	60	1	\$	600.00
4	TO R&R REAR BOOT MECHANISM	60	1	\$	400.00
5	TO R&R REAR WINDSCREEN	11 X	1	\$	400.00
6	TO RNR FUEL TANK TO ASSIST WORK LOAD	11 X	1	\$	450.00
7	TO R&R UPHOLSTERY, GARNISH AND ATTACHMENT PART	80	1	\$	600.00
8	TO CHECK CARPLATE LAMP AND TEST FUNCTION	11 X	1	\$	150.00
9	TO CHECK REVERSE SENSOR AND TEST FUNCTION	50	1	\$	150.00
10	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION	20	1	\$	150.00
11	TO CHECK WIRING LAYOUT AND BOOTLID THIRD BRAKE LAMP FUNCTION		1	\$	150.00
12	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	11 X	1	\$	150.00
13	TO DO WATER LEAK TEST	11 X	1	\$	120.00
14	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11 X	1	\$	450.00
15	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	11 X	1	\$	800.00

L: \$2170

Total: \$18,174.70

- 20% = \$10,550

LKR Auto Consumer is hence notify

TOTAL

\$ 11,170.00

(The Responder of the following)

GRAND TOTAL COST

\$ 17,820.00

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

41,745.60

PAGE 2 OF 2

P- 4825

102

P- 4342.50

S- 940.00

L- 2220.00

7502.5