

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 16/09/2020
TP Veh Reg No: SLD72D

Estimate No: EST2000197
Date: 18 Sep 2020

Veh Reg No: SGR6118C
Make/Model: SEAT TARRACO XCELL
1.4TSI 150 6AT
Chasis No: VSSZZZKNZLW016200
Reg. Date: 29/05/2020
Your Ref No: SLD72D

Justin.

Estimate Repair Cost to Vehicle No :SGR6118C

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented</i>	2,275.00 ✓	1850
2	1 PC BOOTLID LOGO <i>new</i>	80.00 ✓	
3	1 PC BOOTLID "TARRACO " EMBLEM <i>new</i>	75.00 ✓	
4	1 PC BOOTLID "R/H" EMBLEM <i>new</i>	60.00 ✓	
5	1 PC BOOT LID CHROME <i>Dented</i>	320.00 ✓	
6	1 PC BOOT LID LAMP RH <i>crushed</i>	505.00 ✓	410
7	1 PC REAR BUMPER CENTRE REFLECTOR LIGHT <i>crushed</i>	495.00 ✓	420
8	1 PC REVERSE CAMERA	850.00 X	
9	1 PC BOOT LID RUBBER	225.00 X	
10	1 PC BOOT LID LOCK	210.00 X	
11	1 PC TAIL LAMP - RH	595.00 X	
12	1 PC REAR PANEL <i>Repis</i>	750.00 X	
13	1 PC REAR PANEL TRIM <i>new</i>	230.00 X	
14	1 PC REAR BUMPER <i>Defound</i>	1,945.00 ✓	1600
15	1 PC REAR LOWER BUMPER <i>Defound</i>	570.00 ✓	
16	4 PCS REVERSE SENSORS <i>2 pieces damaged</i>	1,184.00 ✓	592
17	1 PC REAR LOWER BUMPER REFLECTOR - RH <i>crushed</i>	75.00 ✓	
18	1 PC REAR BUMPER REINFORCEMENT <i>Best</i>	670.00 ✓	
19	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	190.00 ✓	
20	2 PCS REAR BUMPER SIDE CHROME <i>new</i>	260.00 ✓	
21	1 PC REAR CENTRE PAD <i>Defound</i>	690.00 ✓	
22	1 PC REAR BUMPER SPONGE <i>Defound</i>	175.00 ✓	
23	1 PC REAR BLIND SPOT SENSOR <i>Damaged</i>	780.00 ✓	
24	1 PC BOOT LID LOCK SENSOR <i>Damaged</i>	190.00 ✓	
		13,399.00	
		Less 10%	1,339.90
			12,059.10
	Special Net		
25	1 PC REAR NUMBER PLATE <i>crushed</i>	50.00 ✓	

9947

8952.30

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2000197

Date: 18 Sep 2020

Veh Reg No: SGR6118C

Make/Model: SEAT TARRACO XCELL
1.4TSI 150 6AT

Chasis No: VSSZZZKNZLW016200

Reg. Date: 29/05/2020

Your Ref No: SLD72D

Claim Type: Third Party

Accident Date: 16/09/2020

TP Veh Reg No: SLD72D

Estimate Repair Cost to Vehicle No :SGR6118C

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
26	1 PC REAR WINDSCREEN SEAL	60.00	40
27	1 PC REAR WINDSCREEN SEALANT	60.00	40
28	1 SET REAR PANEL TRIM CLIPS	60.00	X
		230.00	230.00
	Labour		
29	1 TO CHECK WIRING	50.00	30
30	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00	50
31	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
32	1 TO REFIX THIRD BRAKE LIGHT	100.00	X
33	1 TO REMOVE AND REFIT INNER TRIM	100.00	80
34	1 TO REMOVE AND REFIT REVERSE CAMERA	100.00	50
35	1 TO SPRAY UNDERSEAL	180.00	40
36	1 TO SPRAY PAINTING	1,200.00	700
37	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	600
	To Re-programme	300 180	3.150.00 - 3.150.00
	To apply paint protection.	600 400	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

Estimate No: EST2000197

Date: 18 Sep 2020

Veh Reg No: SGR6118C

Make/Model: SEAT TARRACO XCELL
1.4TSI 150 6AT

Chasis No: VSSZZZKNZLW016200

Reg. Date: 29/05/2020

Your Ref No: SLD72D

Claim Type: Third Party

Accident Date: 16/09/2020

TP Veh Reg No: SLD72D

Estimate Repair Cost to Vehicle No :SGR6118C

Quantity	Description	List Price S\$	Amount S\$
		Total	S\$ 15,439.10
		Add GST @ 7%	1,080.74
		Total Amount Payable	S\$ 16,519.84

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND FIVE HUNDRED NINETEEN AND CENTS EIGHTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
1/5 18/09/20.
08 Days.

total 11332.30
1/51 9K

8750
81C
062p