

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0646/2020/NS
DATE	:	9-Sep-20
WIP	:	48271

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SKP 5546 U

EQ INSURANCE COMPANY LIMITED

22 GEMMILL LANE

SINGAPORE 069257

Motor Claims Dept

Tel: 6223 9433 - Fax: 6223 4190

OWNER'S NAME	:	MR SIM SHAO QUAN(SHEN SHAOQUAN)
ADDRESS	:	96B HENDERSON ROAD
		#38-72
		SINGAPORE 152096
TELEPHONE	:	HP +65 97885225
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	5118238328
VEHICLE NO	:	SLR 4765 M
MODEL CODE	:	AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR	:	16/8/2017
ENGINE NO	:	CHZ 397933
CHASSIS NO	:	WAUZZZGA9JA001351
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	15-Sep-20
PLACE OF ACCIDENT	:	CLUB STREET LAMP POST NUMBER 10

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 4765 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRNSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	80 ✓
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00	80 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,672.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 4765 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>Regis</i>		\$	1,164.00	X
2 REAR BUMPER FIXING PARTS <i>Regis</i>		\$	76.00	X
3 REAR BUMPER SPOILER <i>Regis</i>		\$	281.00	X
4 REAR BUMPER TOWING EYE COVER <i>Regis</i>		\$	43.00	X
5 REAR LIGHT REFLECTOR - RH ?		\$	30.00	?
6 TAIL LIGHT <i>2</i>		\$	1,306.00	X
7 TAIL LIGHT TRIM <i>Regis</i>		\$	30.00	+
8 REAR BUMPER CARRIER		\$	544.00	+
9 REAR BUMPER HOLDING STRAP - LH / RH <i>2</i>	2	\$	26.00	+
10 REAR PARKING AID SENSOR - OUTER <i>2</i>			TBC	+
11 REAR PARKING AID SEAL RING <i>4</i>	4	\$	14.00	+
12 REAR WHEEL COVER - LH / RH <i>Regis</i>	2	\$	336.00	✓
13 SUNDRIES		\$	200.00	X
TOTAL SPARE PARTS	:	\$	4,050.00	
TOTAL LABOUR CHARGES	:	\$	2,672.00	
GRAND TOTAL	:	\$	6,722.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan
SURVEYED DATE : 18/09/201
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT