



CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE



CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Reg No : 199405410K

Ster (LKK) 83228812

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name - /Chin Leong Yong Reg No/Reg Date SDK6168E / 27/05/201 Date In/Mileage / 0 Chassis No KNAFZ411MG5570090 Engine No G4FGFH608138 Make/Model KIA/FORTE K3 1.6 A SX ADQ Colour/Trim D7U / WK

12 days 22/9/20, 11:30 am

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/09/2020/ 17:39	BLC	247 / DonBong	21412			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3200 3600.00
RENEW REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT								
REAR LAMP HOUSING RH, SPOILAR. REPAIR REAR FENDER RH, REAR CHASSIS RH 400								60 300.00
E PNT88000								240 300.00
REMOVE & INSTALL PARKING SENSOR								
E PNT88000								1750 2800.00
REMOVE & INTALL REAR COMPARTMENT TRIMS, SEATS,								
E PNT98000								30.00
SPRAY PAINT FOR REAR BUMPER, END PANEL, BOOTLID, REAR COMPARTMENT 350								
REAR LAMP HOUSING RH, REAR FENDER RH, SPOILAR								120.00
A 90000001								40.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								40.00
M SUNDRY								120.00
C&C LOGO								
M SUNDRY								400.00
APPLY SEALANT FOR ACCIDENT PORTION								
A 90000001								20.00
RENEW EXHAUST SYSTEM 200								
M SUNDRY								50.00
Sundry								
M SUNDRY								1000.00
REAR NUMBER PLATE WITH FRAME CUT								
A PNT88100								632.80
TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT					1.00	791.00	20.00	
M COVER-RR BUMPER / DO					1.00	245.00	20.00	196.00
M COVER-RR BUMPER, UPR / BR					1.00	42.00	20.00	33.60
M COVER-RR BPR UNDER / mis					1.00	173.00	20.00	138.40
M WIRING HARNESS-BWS EXT / X HM					1.00	365.00	20.00	292.00
M BEAM-RR BUMPER / BR					1.00	5.00	20.00	8.00
M BRACKET-RR BEAM LWR MTG / BR					1.00			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Chin Leong Yong Reg No/Reg Date S0K6168E / 27/05/201 Date In/Mileage / 0 Chassis No KNAFZ411MG5570090 Engine No G4FGFH608138 Make/Model KIA/FORTE K3 1.6 A SX ADQ Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/09/2020/ 17:39	BLC	247 / DonBong	21412			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM LWR,CTR	OR			1.00	5.00	20.00	4.00
M	ANTENNA ASSY-SMARTKEY	X NN			1.00	69.00	20.00	55.20
M	BRACKET-RR RAIL UPR MTG,RH	OT			1.00	4.00	20.00	3.20
M	BRACKET-RR RAIL UPR MTG,LH	? X NN			1.00	4.00	20.00	3.20
M	STAY-RR BUMPER RH	OR			1.00	75.00	20.00	60.00
M	STAY-RR BUMPER LH	? X NN			1.00	75.00	20.00	60.00
M	BRACKET-RR BUMPER SIDE MTG,RH	OR			1.00	33.00	20.00	26.40
M	BRACKET-RR BUMPER SIDE MTG,LH	? X NN			1.00	33.00	20.00	26.40
M	PANEL ASSY-TRUNK LID	OD			1.00	1365.00	20.00	1092.00
M	HINGE ASSY-TRUNK LID,RH	OT			1.00	68.00	20.00	54.40
M	PANEL ASSY-BACK	OD			1.00	372.00	20.00	297.60
M	PNL ASSY-RR FLOOR RR COMPLETE	OD			1.00	602.00	20.00	481.60
M	PANEL ASSY-RR COMB LAMP HSG,RH	OT			1.00	123.00	20.00	98.40
M	TRIM T/LID	X NN			1.00	82.00	20.00	65.60
M	LATCH ASSY-TRUNK LID	OT			1.00	112.00	20.00	89.60
M	W/STRIP-TRUNK LID OPNG	CRU			1.00	100.00	20.00	80.00
M	LOGO ASSY-KIA SUB	NC			1.00	37.00	20.00	29.60
M	EMBLEM-CERATO	NC			1.00	35.00	20.00	28.00
M	TRIM-TRANSVERSE RR	OR			1.00	58.00	20.00	46.40
M	MAT ASSY-LUGGAGE COVERING	X NN			1.00	159.00	20.00	127.20
M	TRIM ASSY-LUGGAGE SIDE RH	CRU			1.00	161.00	20.00	128.80
M	SPOILER-RR	? X NN			1.00	590.00	20.00	472.00
M	LAMP ASSY-REAR COMB INSIDE,RH	CUT			1.00	710.00	20.00	568.00
M	LAMP ASSY-REAR COMB INSIDE,LH	CUT			1.00	710.00	20.00	568.00
M	LAMP ASSY-REAR COMBINATION,RH	BR			1.00	843.00	20.00	674.40
M	LAMP ASSY-REAR COMBINATION,LH	CUT			1.00	843.00	20.00	674.40
M	ULTRASONIC SENSOR ASSY-FBWS	BR			2 4.00	187.00	20.00	598.40
M	MUFFLER ASSY-REAR	OT			1.00	729.00	20.00	583.20
M	PROTECTOR-HEAT REAR	OT			1.00	60.00	20.00	48.00

Confirm & accepted by
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No other charges

Authorized signatory and company stamp

Nett 17,124.80
 7% GST on 17124.80 1198.74
Total Payable 18,323.54

Supplementary items must be resurveyed and confirmed by the repairer within 14 days from date of quote. This is a computer generated document, no signature is required. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.