

22/09/2020

ASS. REC. BY:

REF:

Special Instruction:

Surveyor: Hock Ann
Xinyi (Seah Ong)

ASSIGNMENT (Office)

22/09/2020

From (Person):

of

ACM (ACA)

Date/Time:

16.10.19 10.00a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMP 2050D

Insured:

PBP 3629J

at Workshop m/s

Teamwork

Tel:

68442475

of

Blk 53 Ubi Ave 1 #01-24

Policy No:

Claim No:

S9M02309

Sum Insured:

Excess:

D.O.A. 14.10.19

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

imp

H.O.D. Endorsement:

Date/Time:

16.10.19 10.00a.m

Person Contacted:

Darnen

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBP 3629J NA/LIP/ACI 8027/24 DOB: 14/10/2019
	SMP 2050D NA/LIP/ACI 8027/24 DOB: 14/10/2019
	Dismantle: 16/10/2019.
	After repair: 21/10/2019.

REQ. BY: H-M/VW

REF: Asm (A4)

ASSIGNMENT

From: Des

Date: 16/10.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMP 2050D

at Workshop m/s Teamwork Garage
of BIK 53 ub Ave 1 A01-24

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$84K

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Smp 2050D

Yr Regn:

13/09/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T-SIENTA HYBRID c.c. 1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

7266km

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NHP170717.4281

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/60R5

R: 185/60R5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fit and for same (BS)

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

14/10/19

D.O.I.

16/10/19 5.15pm

Survey held at

Teamwork

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or .

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

		<u>Smp 2050D</u>
		<u>(PRS) cash</u>
		<u>Range - 3.5-4.5L</u>
		<u>Repair Days - 5</u>
	<u>MV - 84000</u>	
	<u>PV - 33930</u>	
	<u>NV - 50000</u>	
		<u>25/10/2019</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Ref. Form: PRS

Lump Sum / P.P. /