

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0679/2020/NS
DATE : 18-Sep-20
WIP : 49920

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SKW 1260 H

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MS MERRY GUNAWAN
ADDRESS : 11 NATHAN RD
#23-03
SINGAPORE 248732
TELEPHONE : HP +65 97555277
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00698903
VEHICLE NO : **SDM 8858 Z**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 27/9/2017
ENGINE NO : DAX 012912
CHASSIS NO : WAUZZZF3H2048510
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Sep-20
PLACE OF ACCIDENT : NEW BRIDGE ROAD TOWARDS KEONG SARK ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDM 8858 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	800
3	TO RESPRAY REAR TOP BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$ 2,800.00	2000 - 800 x 2 = 1600 Arch x 2 = 200 x 2 = 400
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,552.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 8858 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR UPPER BUMPER <i>3 Repairs</i>		\$	1,724.00	+
2 REAR LOWER BUMPER		\$	1,182.00	+
3 REAR SPOILER <i>new cut</i>		\$	830.00	✓
4 REAR BUMPER TOWING EYE COVER - LH		\$	48.00	+
5 REAR BUMPER TOWING EYE COVER - RH		\$	29.00	+
6 REAR BUMPER CLOSING ELEMENT - LH / RH <i>2</i>	2	\$	190.00	+
7 REAR BUMPER TRIM - LH / RH <i>2</i>	2	\$	468.00	+
8 TAIL LIGHT - LH / RH <i>2</i>	2	\$	1,382.00	+
9 BOOT LID CONTROL UNIT <i>2</i>		\$	399.00	+
10 REAR BUMPER CARRIER		\$	911.00	+
11 REAR BUMPER HOLDING STRAP		\$	166.00	+
12 REAR PARKING AID SENSOR <i>2</i>	2		TBC	+
13 REAR PARKING AID SEAL RING <i>2</i>	4	\$	14.00	+
14 REAR WHEEL COVER - LH / RH <i>2</i>	2	\$	1,154.00	✓
15 SUNDRIES <i>?</i>		\$	250.00	?
TOTAL SPARE PARTS	:	\$	8,747.00	
TOTAL LABOUR CHARGES	:	\$	4,552.00	
GRAND TOTAL	:	\$	13,299.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lg*
SURVEYED DATE : *25/09/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT