

DATE: 29/9/2020

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	: YP8264Y
Make & Model	: HINO / HINO XZU710R-HKFMS3
Chassis No.	: JHHUCS3H60K022754
Engine No.	: N04CUS34694
Manufactured Year	: 2017
Labour	: REPAIRER'S
TP Vehicle Reg No.	: PC6965X
DOA & Location	: 17/11/2019 ALONG SENTOSA'S COVE AVE ROUNDABOUT
Our Ref	: YP8264Y / OJJ FOODS PTE LTD

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,200.00
2	SPRAYPAINTING	\$ 1,200.00
Total Labour (S\$)		\$ 2,400.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	TAILDOOR RH <i>cut</i>	\$ 2,500.00
2	TAILDOOR HINGE RH UPPER <i>bt</i>	\$ 300.00
3	TAILDOOR HINGE RH LOWER <i>X SVC</i>	\$ X 300.00
4	TAILDOOR RUBBER RH X4 <i>cut</i>	\$ 1,200.00
5	TAILDOOR SIDE ALUMINIUM PANEL RH <i>X SVC</i>	\$ X 800.00
6	TAILDOOR INNER CHESSPLATE <i>X SVC</i>	\$ X 800.00
7	STICKER TAILDOOR RH <i>nn s/n</i>	\$ 1,200.00
8	HINGE BOLTS <i>X SVC</i>	\$ X 200.00
9	END PANEL <i>bt s/n</i>	\$ 800.00
10	STICKER RH REAR <i>X NN</i>	\$ X 1,200.00
Total Miscellaneous Items (S\$)		\$ 9,300.00

Total Parts (S\$)	\$ -
Total Labour (S\$)	\$ 2,400.00
Total Miscellaneous (S\$)	\$ 9,300.00
Sub-Total (S\$)	\$ 11,700.00
GST 7% (S\$)	\$ 819.00
Grand Total (S\$)	\$ 12,519.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

47P.
Rental
500 } 1000
500 } 1000
to check ? parts prices.
400 } 700 s/n
300 }
1000
700
3105
4805
20%
3844
4/5-3,850
4 days
4/5
29/09/2020 @ 1355
Reg after repair