



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI20010141/Kqf3e2	
			Date: 14/05/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBH 9836E
	Policy No.	DHOM110165261801	Coverage (\$)	0.00
	Claim No.	M11D10782009	Excess (\$)	1,000.00
	Assign From	CHRISTINA WONG	Assign Date	22/09/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y90K211754	Colour	BLUE
	Odometer	40552 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
	R/H Rear Tyre	155 R12X8 (D)	WEST LAKE	9/9 mm
	L/H Rear Tyre	155 R12X8 (D)	WEST LAKE	9/9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/09/2020	Inspection Date	19/10/2020
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE MARKET VALUE IS S\$57,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	