



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0686/2020/NS
DATE : 21-Sep-20
WIP : 50163

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR YEO KHEE ENG
ADDRESS : BLK 614 ANG MO KIO AVENUE 4
#11-1007
SINGAPORE 560614
TELEPHONE : HP +65 96884398
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900013358
VEHICLE NO : SKS 8628 G
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 31/1/2019
ENGINE NO : CVK 075735
CHASSIS NO : WAUZZZF49KN006460
MILEAGE : 19516KM
DATE IN : 21-Sep-20
ESTIMATED BY : JOHNNY BOO / ALLAN WJ
ACCIDENT DATE : 18-Sep-20
PLACE OF ACCIDENT : ANG MO KIO AVE 3(TOWARDS AMK AVE 8 AMK MRT)



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 8628 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00 ✓	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 700.00 ✓ 250 ✓	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,650.00 ✓ 1000 ✓	✓
4	✓ TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 1,600.00 ✓ 1100 ✓	✓
5	TO TOW BACK VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 X	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,702.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8628 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>		\$ 2,171.00	*
2	FRONT BUMPER FIXING PARTS <i>new</i>		\$ 580.00	*
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 70.00	*
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>		\$ 194.00	*
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$ 208.00	*
6	RADIATOR GRILLE <i>could</i>		\$ 1,317.00	✓ 1053.60
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 268.00	*
8	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	2	\$ 123.00	*
9	FRONT BUMPER CARRIER <i>new</i>	2	\$ 795.00	*
10	FRONT BUMPER TOP COVER <i>new</i>	2	\$ 126.00	✓ 100.40
11	CAUTION SIGN STICKER <i>new</i>	2	\$ 14.00	✓ 10.80
12	AIRCON STICKER <i>new</i>	2	\$ 8.00	✓ 5.68
13	LOCK CARRIER BRACKET <i>new</i>	2	\$ 136.00	✓ 108.40
14	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>new</i>	2	\$ 56.00	✓
15	BONNET <i>Detid</i>		\$ 2,763.00	✓ 2210.40
16	BONNET ATTACHMENT PARTS <i>new</i>		\$ 408.00	*
17	BONNET LID HINGE - LH / RH <i>new</i>	2	\$ 602.00	*
18	BONNET IMPACT PROTECTION - CENTRE <i>new</i>		\$ 27.00	✓ 21.52
19	BONNET IMPACT PROTECTION - LH <i>new</i>		\$ 28.00	✓ 21.84
20	BONNET IMPACT PROTECTION - RH <i>new</i>		\$ 27.00	✓ 21.52
SUB TOTAL SPARE PARTS			\$ 9,921.00	



PREMIUM AUTOMOBILES

55 UBI ROAD, 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8628 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT	
21 BONNET STRIKER - LH / RH	2	\$	100.00	*
22 BONNET LID LOCK	2	\$	423.00	*
23 BONNET BOWDEN CABLE - CENTRE	new	\$	57.00	*
24 BONNET BOWDEN CABLE	new	\$	57.00	*
25 BONNET RELEASE LEVER		\$	13.00	*
26 LED HEADLIGHT - LH / RH	2	\$	15,386.00	7693 6154.40
27 LIFT CYLINDER - LH / RH	2	\$	416.00	*
28 RADIATOR AIR GUIDE - LH / RH	2	\$	56.00	*
29 RADIATOR AIR GUIDE - LH / RH	2	\$	24.00	9.36
30 RADIATOR AIR GUIDE - UPPER		\$	16.00	*
31 RADIATOR AIR GUIDE - LOWER		\$	22.00	*
32 FRONT NO PLATE	S/N	\$	60.00	60
33 SUNDRIES	? / nec	\$	250.00	2.24
TOTAL SPARE PARTS	:	\$	26,801.00	
TOTAL LABOUR CHARGES	:	\$	4,702.00	
GRAND TOTAL	:	\$	31,503.00	

ALL CHARGES ARE INCLUSIVE OF GST

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

LEGEND: SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD, 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian
20/09/20
Not Authorised, 05 Days.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKX Auto Consultants hence notify the Repairer of the following:

- To reurvey becauater spray painting
- To display damaged party(s) during reurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental items must be reurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT