




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI20010146/Uvd3e2		
(BUDGET DIRECT INSURANCE)		Date : 06-10-2020		
190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924				
Code : AGI				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJK 6606L	Veh. Inspected	SCA 8889J	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007359	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	22/09/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 520I (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAXG12060DX49601	Colour	BLACK	
Odometer	133736	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	18/09/2020	Inspection Date	24/09/2020	
Survey held at	KAIZEN MOTORS (ENGINEERING) PTE LTD 68 KAKI BUKIT AVENUE 6 #02-12 ARK@KB SINGAPORE 417896			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		