


SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At around 10.30pm, I was driving from Siglap Road and turned into the Sky Road to East Coast Road.

I stopped my car at the Sky Road junction to allow traffic from my right of East Coast Road to pass by. Suddenly, car SJK 6606 L hit my car from the back. My car bumper was cracked and damaged. There was no injury from both parties. My wife Helen Fung Suen Lam was with me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

18/9/20 4 pm

Driver's Signature

(if driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

19 SEP 2020

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Technical Specification Plate:

 bar KPa	
2.4	2.5
240	250
2.8	3.3
280	330
2.2	2.2
220	220
2.6	2.7
260	270

6850996

Manufacturer's Label:

Made in
Germany
5201
475

7 263 981

BAYERISCHE MOTOREN WERKE AG

WBAXC12060DX49601

2220 kg
4310 kg
1- 1070 kg
2- 1280 kg