

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/0689/2020/NS  
DATE : 22-Sep-20  
WIP : 50396

VEHICLE **NOT IN** WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMP 1284 C

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MS LAI FENGJUN  
ADDRESS : BLK 426 BUKIT BATOK WEST AVE 2  
#08-115  
SINGAPORE 650426  
TELEPHONE : HP +65 91907908  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 5099399037-02  
VEHICLE NO : **SKK 8029 C**  
MODEL CODE : AUDI A1 SB 1.4 TFSI S TRONIC  
MODEL YEAR : 30/8/2013  
ENGINE NO : CAX A80652  
CHASSIS NO : WAUZZZ8X5CB217083  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 21-Sep-20  
PLACE OF ACCIDENT : JUNCTION OF BRAS BASAH ROAD AND VICTORIA ST

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKK 8029 C**

| S/N                         | NATURE OF JOBS                                                                                                                                      | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                       | S/N \$ 280.00        | X                          |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.                                                                              | S/N \$ 700.00        | 250                        |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 2,500.00          | 1250.<br><del>1000</del>   |
| 4                           | TO RESPRAY FRONT BUMPER, BONNET, HINGES AND LHS FRONT FENDER.                                                                                       | \$ 3,500.00          | 1650.                      |
| 5                           | TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                               | S/N \$ 280.00        | ✓                          |
| 6                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                      | S/N \$ 192.00        | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                     | <b>: \$ 7,452.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8029 C**

| S/N PARTS DESCRIPTION                              | QTY      | DAMAGED PARTS & PRICES |                 | REMARKS |
|----------------------------------------------------|----------|------------------------|-----------------|---------|
|                                                    |          | S/NETT                 |                 |         |
| 1 FRONT BUMPER <i>assembled</i>                    |          | \$                     | 1,466.00        | ✓       |
| 2 FRONT BUMPER FIXING PARTS                        |          | \$                     | 245.00          | +       |
| 3 FRONT BUMPER CLOSING ELEMENT <i>free</i>         |          | \$                     | 165.00          | +       |
| 4 FRONT SPOILER <i>new</i>                         |          | \$                     | 188.00          | +       |
| 5 FRONT BUMPER FOAM FILLER PIECE <i>new</i>        |          | \$                     | 116.00          | +       |
| 6 RADIATOR GRILLE <i>new</i>                       |          | \$                     | 959.00          | +       |
| 7 FRONT BUMPER AIR GUIDE GRILLE - LH ?             |          | \$                     | 208.00          | ?       |
| 8 FRONT REINFORCEMENT BEAM <i>new</i>              |          | \$                     | 684.00          | +       |
| 9 FRONT FENDER - LH <i>Dented</i>                  |          | \$                     | 878.00          | ✓       |
| 10 FRONT FENDER ATTACHMENT PARTS ?                 |          | \$                     | 42.00           | ?       |
| 11 FRONT FENDER BRACKET - CENTRE LH ?              |          | \$                     | 12.00           | ?       |
| 12 FRONT FENDER BRACKET - LH FRONT ?               |          | \$                     | 59.00           | ?       |
| 13 FRONT FENDER BRACE - LH FRONT <i>Bent</i>       |          | \$                     | 53.00           | ✓       |
| 14 FRONT FENDER CLOSING ELEMENT - LH ?             |          | \$                     | 25.00           | ?       |
| 15 WHEEL HOUSING LINER <i>new</i>                  |          | \$                     | 167.00          | +       |
| 16 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i> |          | \$                     | 40.00           | +       |
| 17 BONNET <i>Repis</i>                             |          | \$                     | 2,235.00        | +       |
| 18 BONNET ATTACHMENT PARTS <i>new</i>              |          | \$                     | 137.00          | +       |
| 19 BONNET LID HINGE - LH / RH <i>new</i>           | 2        | \$                     | 252.00          | +       |
| 20 BONNET EDGE PROTECTION - FRONT <i>new</i>       | 2        | \$                     | 40.00           | +       |
| <b>SUB TOTAL SPARE PARTS</b>                       | <b>:</b> | <b>\$</b>              | <b>7,971.00</b> |         |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 8029 C**

| S/N PARTS DESCRIPTION                 | QTY | DAMAGED PARTS & PRICES |                  | REMARKS |
|---------------------------------------|-----|------------------------|------------------|---------|
|                                       |     | S/NETT                 |                  |         |
| 21 HEADLIGHT MOUNTING - LH <i>Mem</i> |     | \$                     | 103.00           | +       |
| 22 HALOGEN HEADLIGHT - LH <i>ht</i>   |     | \$                     | 924.00           | ✓       |
| 23 HALOGEN FOG LAMP <i>Mem</i>        |     | \$                     | 262.00           | +       |
| 24 FRONT ALUMINIUM RIM - LH <i>Ry</i> |     | \$                     | 587.00           | +       |
| 25 FRONT NO PLATE <i>Mem</i>          | S/N | \$                     | 60.00            | +       |
| 26 SUNDRIES <i>?</i>                  |     | \$                     | 250.00           | ?       |
| <b>TOTAL SPARE PARTS</b>              | :   | \$                     | <b>10,157.00</b> |         |
| <b>TOTAL LABOUR CHARGES</b>           | :   | \$                     | <b>7,452.00</b>  |         |
| <b>GRAND TOTAL</b>                    | :   | \$                     | <b>17,609.00</b> |         |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**NAME**

: Adnan Lj

**SURVEYED DATE**

: 23/09/20

**AUTHORISED DATE**

:

**EXCESS COST**

:

**LIABILITY**

:

**REMARKS**

: Not Authorised, 06 Days

**PLEASE NOTE**

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO

MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT